

## 2006 PROTON GEN.2 5 DOOR HATCHBACK

### Asset Details

<b>Build Date:</b>	2006
<b>Compliance:</b>	3/2006
<b>Make:</b>	PROTON
<b>Model:</b>	GEN.2
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	5 DOOR HATCHBACK
<b>Engine Size:</b>	1.6 LITRE 4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	GREY METALLIC
<b>Int. Colour:</b>	
<b>Doors:</b>	
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	46,310	<b>Rego:</b>	XMC-289	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	PL1CM6LNR6G069351	<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>	0				
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	NO	<b>Service Books:</b>	NO

### Features

AIR BAG, AIR CON, CD PLAYER, CENTRAL LOCKING, IMMOBILISER, POWER STEERING, POWER WINDOWS, DEAD BATTERY(SOME BODY REPAIR WORK COMPLETED BEFORE CANCELLATION OF INSURANCE) \*\* NOTE: VEHICLE DEFECTED \*\*

### Tyres

<b>Front LHS:</b>	Poor	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	
-------------------	------	-------------------	---------	------------------	---------	------------------	---------	---------------	--

### Condition

Location	Damage
FRONT LEFT TYRE	SHREDDED & DAMAGED RIM
REAR LEFT RIM	DAMAGED
BODY PANELS	SOME PANELS SCRATCHED
PASSENGER SIDE MIRROR	MISSING