

## 2011 HYUNDAI iLOAD H-1 VAN

### Asset Details

<b>Build Date:</b>	7/2011
<b>Compliance:</b>	8/2011
<b>Make:</b>	HYUNDAI
<b>Model:</b>	iLOAD
<b>Variant:</b>	H-1
<b>Series:</b>	
<b>Body Type:</b>	VAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	5
<b>Seats:</b>	3
<b>Drive Type:</b>	REAR



NO IMAGE AVAILABLE

**MGS**  
Mason Gray Strange



NO IMAGE AVAILABLE

**MGS**  
Mason Gray Strange



NO IMAGE AVAILABLE

**MGS**  
Mason Gray Strange



NO IMAGE AVAILABLE

**MGS**  
Mason Gray Strange

### Asset Identification

<b>Odometer:</b>	112,128kms SHOWING	<b>Rego:</b>	S717 AMB	<b>State:</b>	SA	<b>Expiry:</b>	22/10/2016
<b>VIN:</b>	KMFWBX7JLCU388730	<b>PIN:</b>					
<b>Engine No:</b>	D4CBB866986	<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

ABS, AIR BAG, AIR CON, BLUETOOTH, CARGO BARRIER, CD PLAYER, CENTRAL LOCKING, LADDER RACK, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TOW BAR, POWER MIRRORS

### Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Average
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	---------

### Condition

Location	Damage
REAR TOP SPOT LIGHT	LENSE BROKEN
FRONT BUMPER	CRACKED
WINDSCREEN SIDE STRIP	MISSING
DUCO	DENTS & SCRATCHES