

## DODGE UTILITY

### Asset Details

|                      |            |
|----------------------|------------|
| <b>Build Date:</b>   |            |
| <b>Compliance:</b>   |            |
| <b>Make:</b>         | DODGE      |
| <b>Model:</b>        |            |
| <b>Variant:</b>      |            |
| <b>Series:</b>       |            |
| <b>Body Type:</b>    | UTILITY    |
| <b>Engine Size:</b>  | 6 CYLINDER |
| <b>Transmission:</b> | AUTOMATIC  |
| <b>Fuel Type:</b>    |            |
| <b>Ext. Colour:</b>  |            |
| <b>Int. Colour:</b>  |            |
| <b>Doors:</b>        | 2          |
| <b>Seats:</b>        | 3          |
| <b>Drive Type:</b>   |            |



### Asset Identification

|  |                     |                  |                          |
|--|---------------------|------------------|--------------------------|
| <b>Odometer:</b> 86866 MILES INDICATED | <b>Rego:</b> 166995 | <b>State:</b> SA | <b>Expiry:</b>           |
| <b>VIN:</b>                            | <b>PIN:</b>         |                  |                          |
| <b>Engine No:</b>                      | <b>Hours:</b>       |                  |                          |
| <b>Papers:</b> NO                      | <b>Keys:</b> 0      | <b>Books:</b> NO | <b>Service Books:</b> NO |

### Features

MISSING REAR PANELS, HOOD ORNAMENT IN OFFICE, SUIT WRECK OR RESTORATION

### Tyres

|                        |                        |                       |                       |               |
|------------------------|------------------------|-----------------------|-----------------------|---------------|
| <b>Front LHS:</b> Poor | <b>Front RHS:</b> Poor | <b>Rear LHS:</b> Poor | <b>Rear RHS:</b> Poor | <b>Spare:</b> |
|------------------------|------------------------|-----------------------|-----------------------|---------------|

### Condition

| Location | Damage          |
|----------|-----------------|
| BODY     | RUST THROUGHOUT |