Mason Gray Strange

**Location:** 370-378 Torrens Road, KILKENNY SA 5009

14916-14

# MITSUBISHI MS070 TRACKED EXCAVATOR

## Asset Details

| | |
|---|---|
| **Build Date:** | |
| **Make:** | MITSUBISHI |
| **Model:** | MS070 |
| **Series:** | |
| **Drive Type:** | |
| **Axle Config:** | |
| **Body Type:** | TRACKED EXCAVATOR |
| **Gearbox:** | |
| **Transmission:** | |
| **Engine Make:** | MITSUBISHI |
| **Engine Size:** | 4 CYLINDER |
| **Fuel Type:** | DIESEL |
| **Diff Make / Size:** | |
| **Suspension:** | |
| **Ext Colour:** | |
| **Tyre Size:** | |
| **Tyre Condition:** | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Doors:** | | **Seats:** | | **Length:** | | **Capacity:** | |
| **Volume:** | | **Height:** | | **Width:** | | **GVM:** | |
| **GCM:** | | **SWL:** | | **HP:** | | **Tare:** | |

## Asset Identification

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Odometer:** | | **Rego:** | UUT 525 | **State:** | | **Expiry:** | |
| **VIN:** | | | | **PIN:** | NOT FOUND, N/A | | |
| **Engine No:** | | | | **Hours:** | NOT VISIBLE | | |
| **Papers:** | NO | **Keys:** | | **Books:** | NO | **Service Books:** | NO |

## Features

PUSH BLADE
HAMMER PIPING
MANUAL SINGLE PIN TYPE BUCKET RELEASE
650mm GP TOOTHED BUCKET
1200mm TRIMMING BUCKET

KEY #23

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.

# MITSUBISHI MS070 TRACKED EXCAVATOR

## Condition

| Location | Damage |
|---|---|
| OVERALL CONDITION | COMMENSURATE WITH AGE |
| CABIN | RUSTY / RUST EVIDENT |
| CONTROL ARMS | SLEW, BUCKET & DIPPER CONTROLS STICKY |
| CONTROL ARMS | INTERMITTENT ASSISTANCE REQUIRED ON RETURN |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.