

L5 JOHN DEERE 240 Terra Forma Civil

Year	2000
Make	JOHN DEERE
Model	240
Plant Type	SKID STEER LOADER
Weight	2,811 kgs
Identification No. PIN/VIN	KV0240A241776
Registration No.	KPS 525



Engine Specifications	
Engine displacement	2.9 litre
Number of cylinders	4
Cylinder firing order	
Engine Make	John Deere
Engine No.	

Fluid Specifications		Capacity
Engine Oil Type	Shell Rimula X	7.5 litre
Fuel Type	Diesel	56.7 litre
Hydraulic Oil Type	Shell Tellus 46	22.7 litre
Transmission Fluid Type		
Grease Type / Brand	Shell Retinax HDX2	

Miscellaneous	
Battery size	12V 750CCA
Width, Length & Height	3400, 1700, 2100
Tyre Size / Track Width	10-16.5 NHS Titan HD2000
Tyre Pressure	Max 60 PSI
Ground Engaging Tools	
Bucket Sizes / Width	4 in 1 Sand bucket Broom attachment
	Bolton Edge - A1337HD - 2 1/4 x 5/8 B/Nuts

Part Numbers	Recommended	Equivalent
Ground Engaging		
Air filter	JD KV16428	P827653
Fuel filter	JD RE 62419	P550397
Oil filter	JD T19044	P550020
Fan Belt Sizes		
Alternator Type / Size		
Hydraulic Return	AT314164	P174552
Hydraulic Inline	KV13414 x 2	
Inline Fuel		P550012

Year	2000
Make	JOHN DEERE
Model	240
Plant Type	SKID STEER LOADER
Weight	2,811 kgs
ID No. PIN/VIN)	KV0240A241776
Registration No.	KPS 525



Date	Completed by	Description of Work	Done Hrs/KM's
23/12/2002	Rodney	100 hr service	100.0
28/02/2003	Mick	CE 252 cutting edge	187.0
2/05/2003	Hitachi	250 hr service	250.0
25/11/2003	Hitachi	500 hr service	520.0
12/05/2004	SHANE KELLY	FUEL FILTER	812.7
	JAMES AULICH	OIL,OIL FILTER 250 HR SERVICE	
15/06/2004	Hitachi Aust.	Recall-Pump	
31/12/2004	Scott	Change oil, oil filter, fuel filter, grease all nipples	10.4
6/11/2004	Enzed	Replace blown hose, test, fill with oil, test	
5/04/2005	Brendon	New grease nipples fitted to bucket	
5/05/2005	Brendon	service oil, fuel filters	12721.0
24/08/2005	pirtek	made new hydraulic line to replace burst one	
19/10/2005	Brendon	fit new n70zz battery, check gcharge rate, check for drain	1449.0
24/11/2005	Enzed	replace blown hose	
7/12/2005	Vask	replace dipstick	
12/12/2005	Brendon	service oil, fuel filters, blow out air cleaner, fit new o'ring to fuel fiter mount. clean eng	1521.0
8/02/2006	Bill Turner	rectify inoperative reverse beeper	
22/02/2006	Beaurepairs	repair puncture	
2/02/2006	Pirtek	replace bucket hose	
31/03/2006	Pirtek	replace hose	
13/04/2006	pirtek	tighten bucket fitting	
24/05/2006	Beaurepairs	puncture	
21/07/2006	Adrian Schwab	250 h service	1778
26/07/2006	Hitachi	FEL arm pivot bosses cracks welded, LH 4in1 rod rechromed & new seals fitted. tierod boots replaced. seat tracks repaired	
7/08/2006	Adrian Schwab	starter motor overhauled	
7/08/2006	Beaurepairs	new tyre	
11/08/2006	Beaurepairs	puncture	
17/08/2006	Beaurepairs	puncture	
24/08/2006	Beaurepairs	4 retreads	
3/08/2006	Hitachi	dipstick, coolant	
12/09/2006	Beaurepairs	puncture	
3/10/2006	Beaurepairs	Tyres	
5/10/2006	Hitachi	Ring Gear	
9/10/2006	Hitachi	Rear Engine Mount	
9/10/2006	Mr Sparky	Strip Starter Motor, Replace Pinion Gear & Front Bush	
10/10/2006	Hitachi	Rear Engine Mount & Fan	
11/10/2006	Beaurepairs	Puncture	
11/10/2006	Beaurepairs	Engine Mount	
11/10/2006	Hitachi	Fan Belt	
11/10/2006	NV Picton	Retrimming Seat	
25/10/2006	Beaurepairs	Tyres & Rims	
14/12/2006	Beaurepairs	Fitting Tyre	
19/12/2006	Hitachi	Ignition Key	

13/02/2007	Beaurepairs	Tyre Puncture	
19/02/2007	C & S Wear Parts	Cutting Edge & Shints	
27/02/2007	Hitachi	1000 Hr Service	
14/03/2007	Hitachi	Check & repair Hand Lever Operation	
17/05/2007	Beaurepairs	Fitting New Tyres	
23/10/2007	Beaurepairs	Puncture & Tube Repair	
31/10/2007	Adrian Schwab	Checked coolant, hydraulic oil, flashing light globe	2140
14/11/2007	Enzed	Replace Hydraulic Hose	2162
21/12/2007	Hitachi	Repair seal on pump	2177
10/10/2007	Adrian Schwab	Beacon globe replaced	2139
22/01/2008	Beaurepairs	Puncture Repair	
29/01/2008	Beaurepairs	Puncture Repair	
7/02/2008	Hitachi	Brake switch replaced	2203
13/02/2008	Hitachi	Belt	
18/02/2008	Enzed	Hose & Seal Lock	
26/02/2008	Enzed	Remake Hose Pipe + Oil	
4/03/2008	Hitachi	Seat Belt	
17/03/2008	Hitachi	Ignition Switch	
9/04/2008	Beaurepairs	Puncture Repair	
1/05/2008	Hitachi	Primary Air Element	
5/05/2008	Hitachi	Instrument Cluster	
7/05/2008	Adrian Schwab	250 hr service + New Ins. Panel Fitted	2274
14/05/2008	Motor Traders	Century Battery	
14/05/2008	Hitachi	Alternator	
21/05/2008	Hitachi	Inline Fuel Filter	
22/05/2008	Hitachi	Electrical Connector	
7/07/2008	Beaurepairs	Fitting of 4 New Tube to Tyres	
21/07/2008	Beaurepairs	Puncture Repair	
8/08/2008	Beaurepairs	Puncture Repair	
11/08/2008	Bridgestone Earthmover	Tyre Disposal	
13/01/2009	Hitachi	Brake Hydraulic Cylinder	
22/06/2009	Beaurepairs	Puncture Repair + Rim Repair	
2/07/2009	Enzed	Hoses & male Coupling	
30/07/2009	Hitachi	Service Loader - Inspect Both Final Drive Motors, Replace Hyd. Return & Case Drain, Reassemble with New Parts etc....	
7/08/2009	Enzed	Hoses + Fittings	
15/10/2009	Hitachi	FF/WS Spin-on + Lube Filter Spin-on + Engine Oil	
2/12/2009	Adrian Schwab	250Hr Service Done - AS	3250
2/12/2009	Hitachi	Ignition Key	
31/05/2010	C & S Wear Parts	Cutting Edge & Bolts	
8/06/2010	SOS Tyre Service	Puncture Repair	
5/10/2010	Enzed	Hydraulic Hose, Fem Seal-Lok + Sleeve	
15/10/2010	Hitachi	Engine Oil, Radialseal, FF/WS Spin-On, Lube Filter Spin-On etc..	
18/10/2010	Adrian Schwab	250 Hr Service Done - AS	5400
27/10/2010	Enzed	Female Elbow & Swivel + Hose	
3/11/2010	Baxters	Combo Led Light, Load Resistor, Lamp Red + Round Small Led	
14/12/2010	SOS Tyre Service	Strip & Fit - Change Over	
25/03/2011	SOS Tyre Service	Strip & Fit - Change Over	
28/03/2011	SOS Tyre Service	4 New Power Trax Tyres	
4/05/2011	Enzed	Male Connector + Female Swivel to Male	
21/06/2011	Enzed	2 Hoses Fitted	
26/08/2011	Hitachi	250Hr Service Done	7510
7/02/2012	Hitachi	Replace Tight Centering Plate Slide, 2 struts, link arm bushes, cross shaft bushes	7510
16/02/2012	SOS Tyre Service	Puncture Repair	

2/11/2012	SOS Tyre Service	Puncture Repair	
14/11/2012	Enzed	Repair Hose on Skid Steer	