

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 16-Apr-13 Supplier: Hardy Spicer						
CONFIRMATION ORDER						
Please carry out the following on [REDACTED]s Protec Roller ([REDACTED])						
Find and repair tow hydraulic hose leaks, replace o rings						
Labour	hr	2.5	\$80.00	\$88.00	\$200.00	\$220.00
Consumables	e	1	\$20.00	\$22.00	\$20.00	\$22.00
			<u>Order Totals</u>		<u>\$220.00</u>	<u>\$242.00</u>

Date: 02-Apr-13 Supplier: Hitachi Construction Machinery						
Please carry out the following on [REDACTED]s Protec Roller ([REDACTED])						
Investigate reason why rear drum on roller has no vibration working.						
	ea	1	\$1,000.00	\$1,100.00	\$1,000.00	\$1,100.00
			<u>Order Totals</u>		<u>\$1,000.00</u>	<u>\$1,100.00</u>

Date: 25-Mar-13 Supplier: Barrys Auto Electrical						
CONFIRMATION ORDER						
Please carry out the following on [REDACTED]s Protec Roller ([REDACTED])						
Replace hand brake switch contact						
	ea	1	\$165.50	\$182.05	\$165.50	\$182.05
			<u>Order Totals</u>		<u>\$165.50</u>	<u>\$182.05</u>

Date: 25-Mar-13 Supplier: Barrys Auto Electrical						
CONFIRMATION ORDER						
Please carry out the following on [REDACTED]s Protec Roller ([REDACTED])						
Repair vibration on rear drum						
	ea	1	\$219.50	\$241.45	\$219.50	\$241.45
			<u>Order Totals</u>		<u>\$219.50</u>	<u>\$241.45</u>

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
[REDACTED] Date: 25-Mar-13 Supplier: Hardy Spicer						
CONFIRMATION ORDER						
Please carry out the following on [REDACTED] Protec Roller [REDACTED]						
Inspect vib on roller not working						
Labour	hr	2.5	\$80.00	\$88.00	\$200.00	\$220.00
				<u>Order Totals</u>	<u>\$200.00</u>	<u>\$220.00</u>

[REDACTED] Date: 26-Feb-13 Supplier: Barrys Auto Electrical						
CONFIRMATION ORDER ONLY						
[REDACTED] roller						
Repair rear park brake wiring	ea	1	\$185.45	\$204.00	\$185.45	\$204.00
				<u>Order Totals</u>	<u>\$185.45</u>	<u>\$204.00</u>

[REDACTED] Date: 10-Dec-12 Supplier: JCB Construction Equipment Australia (SA)						
CONFIRMATION ORDER						
Please carry out the following on [REDACTED] Protec Roller [REDACTED]						
Supply and fit new battery, repair flashing beacon, repair water sytem on roller	ea	1	\$467.20	\$513.92	\$467.20	\$513.92
				<u>Order Totals</u>	<u>\$467.20</u>	<u>\$513.92</u>

[REDACTED] Date: 16-Nov-12 Supplier: JCB Construction Equipment Australia (SA)						
Please carry out the following on [REDACTED] Protec Roller [REDACTED]						
Service roller, filters , oils etc and replace vib switch, includes labour, consumables	ea	1	\$732.94	\$806.23	\$732.94	\$806.23
				<u>Order Totals</u>	<u>\$732.94</u>	<u>\$806.23</u>

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 16-May-11 Supplier: Somerled Services						
Please carry out the following to the [REDACTED] 3T Protec Sprinter						
Travel to site - [REDACTED] Check handbrake; test vib switches, order parts, fit switches, modify mount and fit handbrake switch	ea	1	\$1,369.16	\$1,506.08	\$1,369.16	\$1,506.08
All work approval is to be through [REDACTED]						
Order Totals					\$1,369.16	\$1,506.08

Date: 06-May-11 Supplier: Somerled Services						
CONFIRMATION ORDER						
Please carry out the following to the [REDACTED] Protec Sprinter						
Check electrical system and forward and reverse lever. Remove control box and lever - workshop for repairs. Return and refit. Adjust and test. Fit 2 lights to machine.	ea	1	\$1,321.90	\$1,454.09	\$1,321.90	\$1,454.09
All work approval is to be through [REDACTED]						
Order Totals					\$1,321.90	\$1,454.09

Date: 28-Mar-11 Supplier: Somerled Services						
CONFIRMATION ORDER						
Please carry out the following to the Protec Sprinter						
Repair throttle and check lighting	ea	1	\$515.40	\$566.94	\$515.40	\$566.94
Order Totals					\$515.40	\$566.94

Date: 11-Feb-11 Supplier: Hitachi Construction Machinery						
CONFIRMATION ORDER						

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 11-Feb-11 Supplier: Hitachi Construction Machinery						
• WS400102927 PROTEC 226 ROLLER, Serial 0220. Travel to [REDACTED] and jumpstart machine and return to workshop. Replace seat switch, replace joystick rubber, replace throttle cable, remove oil cooler and weld up cracks. Refit and test operation. Weld up [REDACTED]	ea	1	\$2,292.89	\$2,522.18	\$2,292.89	\$2,522.18
Order Totals					\$2,292.89	\$2,522.18

Date: 03-Feb-11 Supplier: Hitachi Construction Machinery						
CONFIRMATION ORDER						
Protec 226 Roller Serial 022 [REDACTED] WS4001022856 \$781.50+ repair start fault on 226 roller serial 0221 at [REDACTED] This work was carried out on site at [REDACTED] before fwd/rev mechanism failed and it came back to shop and machine failed afterwards which caused it to go into workshop for further repairs.	lt	1	\$781.50	\$859.65	\$781.50	\$859.65
Order Totals					\$781.50	\$859.65

Date: 31-Jan-11 Supplier: Hitachi Construction Machinery						
CONFIRMATION ORDER						
Repair broken housing on forward/reverse lever, replace cable and seat switch. Repair fuel fault and test operation in workshop	ea	1	\$3,055.29	\$3,360.82	\$3,055.29	\$3,360.82
Order Totals					\$3,055.29	\$3,360.82

Date: 17-May-10 Supplier: Hitachi Construction Machinery						
Travel to [REDACTED] and carry out 2000 hour service on [REDACTED] Protec DV226 Roller [REDACTED] Current hours: 2136	it	1	\$950.40	\$1,045.44	\$950.40	\$1,045.44
Order Totals					\$950.40	\$1,045.44

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 05-Jan-09 Supplier: Hitachi Construction Machinery						
Travel to [REDACTED] and repair vibration control on [REDACTED]s Protec DV226 Roller (part [REDACTED])	1		\$404.50	\$444.95	\$404.50	\$444.95
				<u>Order Totals</u>	<u>\$404.50</u>	<u>\$444.95</u>
Date: 19-Dec-08 Supplier: Hitachi Construction Machinery						
Travel to [REDACTED] and repair forward / reverse lever on [REDACTED] Protec DV226 Roller (part [REDACTED])	1		\$576.20	\$633.82	\$576.20	\$633.82
				<u>Order Totals</u>	<u>\$576.20</u>	<u>\$633.82</u>
Date: 28-Nov-08 Supplier: Hitachi Construction Machinery						
Travel to [REDACTED] and carry out the following repairs on [REDACTED] Protec DV226 Roller (part [REDACTED]) Inspect reverse alarm activated all the time. Adjust forward/reverse lever. Fit new pins to seat switch. Test, all ok.	1		\$374.20	\$411.62	\$374.20	\$411.62
				<u>Order Totals</u>	<u>\$374.20</u>	<u>\$411.62</u>
Date: 30-Jun-08 Supplier: Hitachi Construction Machinery						
Repair large oil leak from hydraulic drive motor on [REDACTED]s Protec DV226 Roller (part [REDACTED]) Supply and fit new hydraulic drive motor and hoses.	1		\$4,232.15	\$4,655.36	\$4,232.15	\$4,655.36
				<u>Order Totals</u>	<u>\$4,232.15</u>	<u>\$4,655.36</u>
Date: 30-Jun-08 Supplier: Hitachi Construction Machinery						
Carry out the following works on [REDACTED]s Protec DV226 Roller (part [REDACTED]) Travel to [REDACTED] and repair vibration system not working. Transport machine back to workshop for further investigation. repair roller shaft, replace bearings on rear vibration drum shaft. Replace coupling.	1		\$4,064.12	\$4,470.53	\$4,064.12	\$4,470.53

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 30-Jun-08 Supplier: Hitachi Construction Machinery						
					<u>Order Totals</u>	\$4,064.12 \$4,470.53

Date: 28-May-08 Supplier: Hitachi Construction Machinery						
Travel to [REDACTED] and repair non operational vibration on Protec DV226 Roller [REDACTED]		1	\$333.60	\$366.96	\$333.60	\$366.96
					<u>Order Totals</u>	\$333.60 \$366.96

Date: 23-Jan-08 Supplier: Hitachi Construction Machinery						
travel to [REDACTED] and repair starting problem on [REDACTED] protec 226 roller [REDACTED] replace battery. Replace fuel lift pump and fuel filter parts labour		1 1	\$365.95 \$720.00	\$402.55 \$792.00	\$365.95 \$720.00	\$402.55 \$792.00
					<u>Order Totals</u>	\$1,085.95 \$1,194.55

Date: 21-Jan-08 Supplier: Hardy Spicer						
travel to [REDACTED] and replace blown hydraulic hose on [REDACTED] protec DV226 roller [REDACTED]		1	\$375.92	\$413.51	\$375.92	\$413.51
					<u>Order Totals</u>	\$375.92 \$413.51

Date: 06-Dec-07 Supplier: Barrys Auto Electrical						
travel to [REDACTED] and check battery [REDACTED]s protec roller [REDACTED] reported to be having starting problem. Inspect and test battery. Check charging system, all ok.		1	\$33.50	\$36.85	\$33.50	\$36.85
					<u>Order Totals</u>	\$33.50 \$36.85

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 28-Nov-07 Supplier: Hitachi Construction Machinery						
while on site, remove mesh guards on [REDACTED] protec DV226 roller (pe3041)		1	\$151.04	\$166.14	\$151.04	\$166.14
			<u>Order Totals</u>		\$151.04	\$166.14
Date: 05-Sep-07 Supplier: Burns Logistics PTY LTD						
PICKUP Wednesday 5/9 @ 3pm: [REDACTED] protec 3t roller [REDACTED] from [REDACTED]	hr	2	\$74.00	\$81.40	\$148.00	\$162.80
DELIVERY: [REDACTED] central 9, opposite school, the strand, mawson lakes.						
Thursday 6/9 @ 3pm: [REDACTED] protec 3t roller [REDACTED] from mawson lakes and return to northfield tilt tray required at hourly rate (approx 4 hours)	hr	2	\$74.00	\$81.40	\$148.00	\$162.80
site contacts [REDACTED]						
[REDACTED]						
[REDACTED]						
Personnel while on site are to wear long sleeve shirts & trousers, sun hat, safety boots, reflective vests and eye protection						
The above order is a confirmation of RATE ONLY the quantity & total of value is an estimate only (For [REDACTED] administration purposes) and must not be considered as an implied quantity and/or value under this Purchase Order.						
Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure						
			<u>Order Totals</u>		\$296.00	\$325.60

Date: 21-Aug-07 Supplier: Hitachi Construction Machinery						
[REDACTED] carry out repairs to [REDACTED] protec 226 sprinter roller [REDACTED]						

Orders for Asset [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 21-Aug-07 Supplier: Hitachi Construction Machinery						
repair articulation after machine breaking in half.						
quoted		1	\$3,852.53	\$4,237.78	\$3,852.53	\$4,237.78
Personnel while on site are to wear long sleeve shirts & trousers, sun hat, safety boots, reflective vests and eye protection						
Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure.						
Order Totals					\$3,852.53	\$4,237.78

Date: 08-Aug-07 Supplier: Karl Dell Haulage						
Supply the following						
shift [REDACTED] protec 3 tonne roller ([REDACTED]) from hitachi cavan to catcon's site, follland ave, northfield						
tilt tray required	hr	2	\$55.00	\$60.50	\$110.00	\$121.00
booked for Wednesday 8/8/07						
Personnel while on site are to wear long sleeve shirts & trousers, sun hat, safety boots, reflective vests and eye protection						
Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure						
Order Totals					\$110.00	\$121.00

Date: 03-Aug-07 Supplier: Freo Machinery						
ATTN LINDA						
Supply the following						

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 03-Aug-07 Supplier: Freo Machinery load [REDACTED] protec roller ([REDACTED]) onto toll express truck crane required at hourly rate Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure						
		1	\$143.00	\$157.30	\$143.00	\$157.30
			<u>Order Totals</u>		<u>\$143.00</u>	<u>\$157.30</u>

Date: 30-Jul-07 Supplier: Performance Towing Supply and deliver collect [REDACTED] 3t roller ([REDACTED]) from toll express, 22 peddar crescent, regency park and deliver to [REDACTED] Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure						
			<u>Order Totals</u>		<u>\$0.00</u>	<u>\$0.00</u>

Date: 26-Mar-07 Supplier: Higgy's Mechanical Supply the following Carry out the following repairs to [REDACTED] Protec DV226 Roller ([REDACTED]): Replace broken drum rubbers [REDACTED] Repair broken spray bar. Conduct full machine service, change oils, replace air, oil and fuel filters. Labour Parts Sublet welding repairs to mount holes for rubbers						
		1	\$960.00	\$1,056.00	\$960.00	\$1,056.00
		1	\$220.00	\$242.00	\$220.00	\$242.00
		1	\$150.00	\$165.00	\$150.00	\$165.00

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
-------------	------	-----	---------------------	----------------------	---------------------	----------------------

Order No: [REDACTED] Date: 26-Mar-07 Supplier: Higgy's Mechanical

The above order is a confirmation of RATE ONLY the quantity & total of value is an estimate only (For [REDACTED] administration purposes) and must not be considered as an implied quantity and/or value under this Purchase Order.

Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Order No: 61918.888 Date: 26-Mar-07 Supplier: Higgy's Mechanical						
					<u>Order Totals</u>	<u>\$1,330.00</u>
[REDACTED] Date: 02-Mar-07 Supplier: Roller Parts						
Please supply & deliver						
Drum rubber mounts for [REDACTED] Protec Sprinter DV226 3 tonne twin drum roller [REDACTED]	ea	5	\$152.00	\$167.20	\$760.00	\$836.00
Deliver via Express Post and mark "URGENT" Higgy's Mechanical PO Box 402 Waroona WA 6125	pk	1	\$25.00	\$27.50	\$25.00	\$27.50
"The above order is a confirmation of RATE ONLY the quantity & total of value is an estimate only (For [REDACTED] administration purposes) and must not be considered as an implied quantity and/or value under this Purchase Order."						
"Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure."						
					<u>Order Totals</u>	<u>\$785.00</u>
[REDACTED] Date: 18-Oct-06 Supplier: Hitachi Construction Machinery						
Carry out 500hr service on [REDACTED] 3t Protec Sprinter (B [REDACTED])						
Replace seat belt, supply & fit fire extinguisher, replace engine mount, repair electrics, replace battery		1	\$370.05	\$407.06	\$370.05	\$407.06
Parts						

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 18-Oct-06 Supplier: Hitachi Construction Machinery						
Labour		1	\$950.15	\$1,045.16	\$950.15	\$1,045.16
Sub-contract supply of parts		1	\$385.95	\$424.55	\$385.95	\$424.55
			<u>Order Totals</u>		<u>\$1,706.15</u>	<u>\$1,876.77</u>

Date: 17-Oct-06 Supplier: Colour Touch System						
Prepare & Paint [REDACTED] Protec Sprinter Roller ([REDACTED])		1	\$1,400.00	\$1,540.00	\$1,400.00	\$1,540.00
"Payment will not be made on invoice amounts exceeding this purchase order value. Authorisation must be provided by [REDACTED] Representative and an additional purchase order must be issued for any expenditure over this purchase order figure."						
			<u>Order Totals</u>		<u>\$1,400.00</u>	<u>\$1,540.00</u>

Date: 10-Oct-06 Supplier: Performance Towing						
Collect [REDACTED] Protec Roller ([REDACTED]) from Hitachi and deliver to [REDACTED] yard at [REDACTED]	hr	2	\$45.00	\$49.50	\$90.00	\$99.00
Hourly rate - approx 2 hrs						
"The above order is a confirmation of RATE ONLY. The quantity & total of value is an estimate only (For [REDACTED] administration purposes) and must not be considered as an implied quantity and/or value under this Purchase Order."						
			<u>Order Totals</u>		<u>\$90.00</u>	<u>\$99.00</u>

Date: 30-May-06 Supplier: Hitachi Construction Machinery						
Travel to site & inspect no vibration fault, joystick button U/S. Soldered terminals on for temporary repair.						
Order new switch. Returned to site & repaired starting fault, replaced fuse.						
Fitted new vibration switch.						

Orders for Asset: 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 30-May-06 Supplier: Hitachi Construction Machinery						
Tested vibration, 2 trips to site required. Ordered 2 switches so we have one spare switch.	1		\$484.93	\$533.42	\$484.93	\$533.42
				<u>Order Totals</u>	<u>\$484.93</u>	<u>\$533.42</u>

Date: 31-May-05 Supplier: Hitachi Construction Machinery						
Carry out full machine steam clean, machine travelling to WA. Carry out full mechanical inspection. Supply & fit fire extinguisher. Supply & fit rotating light (old light broken). Supply & fit 2 way radio in weathproof box. Repair horn circuit. Supply & fit rear work lights. Repair solenoid bracket in front right engine compartment. Fit new drum drive rubbers. Fit new seat assy & repair side slides Repair emergency stop switch. Rescuer rear water rail. 1 Clamp required. Repair engine temperature gauge. Repair front bonnet, adjusted hinges & replaced engine oil filter. Fitted new dash alarm. Repair cracks in steering column mounts. Repaired forward reverse lever, required neutral start switch adjustment. Provide full machine inspection report. Check over machine to confirm to Ravensthorpe mine requirements.						
Total	1		\$5,451.30	\$5,996.43	\$5,451.30	\$5,996.43
				<u>Order Totals</u>	<u>\$5,451.30</u>	<u>\$5,996.43</u>

Date: 31-Jan-05 Supplier: Hitachi Construction Machinery						
Attended site and inspection problem with Protec 31 Sprinter Roller at Front drum rubbers collapsed. Supply & Fit rubbers. Rate includes labour of approx \$380 and rubbers cost \$905						
	1		\$1,285.00	\$1,413.50	\$1,285.00	\$1,413.50
				<u>Order Totals</u>	<u>\$1,285.00</u>	<u>\$1,413.50</u>

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 29-Oct-04 Supplier: Hitachi Construction Machinery Please attend site at address below & carry out a periodic (1000Hr) service to [REDACTED] Protec Sprinter DV226 Roller Rego WLG-264 CATCON ID PE3041. (Current Hrs 976) Rate is normal Hitachi mechanic rates plus consumables & travel. Supply and fit replacement radiator cap						
	ea	1	\$1,127.19	\$1,239.91	\$1,127.19	\$1,239.91
				<u>Order Totals</u>	<u>\$1,127.19</u>	<u>\$1,239.91</u>

Date: 30-Jul-04 Supplier: Hitachi Construction Machinery To attend site at [REDACTED] & carry out check on charging system protec sprinter roller. Supply and fit replacement battery						
	ea	1	\$191.37	\$210.51	\$191.37	\$210.51
				<u>Order Totals</u>	<u>\$191.37</u>	<u>\$210.51</u>

Date: 24-Jun-04 Supplier: Hitachi Construction Machinery To attend site at [REDACTED] s and carry out repairs to throttle cable reported sticking on full throttle) on Protec Dv-226 twin drum roller (823Hrs						
	lt	1	\$192.10	\$211.31	\$192.10	\$211.31
				<u>Order Totals</u>	<u>\$192.10</u>	<u>\$211.31</u>

Date: 14-Nov-03 Supplier: Hitachi Construction Machinery Please attend site at address below & carry out a periodic (250Hr) service to [REDACTED] Protec Sprinter DV226 Roller Rego WLG-264 [REDACTED] ID [REDACTED]. (Current Hrs 720) Rate is normal Hitachi mechanic rates plus consumables & travel. Please also carry out repairs to damaged rubbers on drum, ensuring only damaged rubbers are replaced. (Approx 5 No)						
		1	\$1,146.81	\$1,261.49	\$1,146.81	\$1,261.49
				<u>Order Totals</u>	<u>\$1,146.81</u>	<u>\$1,261.49</u>

Orders for Asset : [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 14-Oct-03 Supplier: Hardy Spicer						
To attend site at [REDACTED] and carry out repairs to damaged hose on [REDACTED]	1		\$163.97	\$180.37	\$163.97	\$180.37
				<u>Order Totals</u>	\$163.97	\$180.37
Date: 03-Jul-03 Supplier: Enzed - Wingfield						
To attend site & carry out repairs to damaged hose on [REDACTED] Protec Sprinter Roller [REDACTED]	1		\$217.99	\$239.79	\$217.99	\$239.79
				<u>Order Totals</u>	\$217.99	\$239.79
Date: 24-May-03 Supplier: Hitachi Construction Machinery						
Please attend site at address below & carry out a periodic (500Hr) service to [REDACTED] Protec Sprinter DV226 Roller Rego WLG-264 [REDACTED] ID [REDACTED] (Current Hrs 503) Rate is normal Hitachi mechanic rates plus consumables & travel.						
	1		\$146.91	\$161.60	\$146.91	\$161.60
				<u>Order Totals</u>	\$146.91	\$161.60
Date: 09-Jan-03 Supplier: Enzed - Wingfield						
To attend site at [REDACTED] & carry out repairs to Protec Sprinter Roller.	1		\$395.62	\$435.18	\$395.62	\$435.18
				<u>Order Totals</u>	\$395.62	\$435.18
Date: 29-May-02 Supplier: Hitachi Construction Machinery						
Ignition Switch Including Keys	1		\$182.10	\$200.31	\$182.10	\$200.31
Delivery						
				<u>Order Totals</u>	\$182.10	\$200.31
Date: 09-Jan-02 Supplier: Hitachi Construction Machinery						

Orders for Asset [REDACTED] - 3T Protec Sprinter (02)

Description	Unit	Qty	Unit Cost ex GST	Unit Cost inc GST	Line Cost ex GST	Unit Cost inc GST
Date: 09-Jan-02 Supplier: Hitachi Construction Machinery						
Conduct 250hr service to [REDACTED] 3T Protec Roller - approx hrs 237		1	\$227.84	\$250.62	\$227.84	\$250.62
			<u>Order Totals</u>		<u>\$227.84</u>	<u>\$250.62</u>
Date: 12-Nov-01 Supplier: Enzed - Wingfield						
TO ATTEND SITE AND REPAIR BROKEN HOSE ON PROTEC 3T ROLLER		1	\$297.88	\$327.67	\$297.88	\$327.67
Two Drive motor hoses had been rubbing on body to motor.						
1.5mtrs by half inch hoses.						
			<u>Order Totals</u>		<u>\$297.88</u>	<u>\$327.67</u>
Date: 19-Oct-01 Supplier: Beaufreaires (Norwood)						
HEAVY DUTY BATTERY TO FIT PROTEC DV-226 ROLLER.		1	\$98.00	\$107.80	\$98.00	\$107.80
			<u>Order Totals</u>		<u>\$98.00</u>	<u>\$107.80</u>
			<u>Report Totals</u>		<u>\$46,430.01</u>	<u>\$51,073.01</u>