



## 2003 MERCEDES SPRINTER 313 CDI HIGH ROOF FRIDGE VAN

<b>Asset Detail</b>	s						
Build Date:	1/2003						
Compliance:							
Make:	MERCEDES						
Model:	SPRINTER						
Variant:	313 CDI						
Series:		NO IMAGE AVAILABLE					
<b>Body Type:</b>	HIGH ROOF FRIDGE VAN						
Engine Size:	4 CYLINDER						
Transmission:	5 SPEED MANUAL TRANSMISSION						
Fuel Type:	DIESEL						
Ext. Colour:	WHITE DUCO						
Int. Colour:	GREY						
Doors:	2						
Seats:	2	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE	NO IMAGE NAME A FE			
Drive Type:	REAR	AVAILABLE	AVAILABLE	AVAILABLE			

#### **Asset Identification**

Odometer:	243,748kms SHOWING	Rego:	S581 BMM	State:		Expiry:	
VIN:	WDF903662A906072			PIN:			
Engine No:				Hours:			
Papers:	NO	Keys:	1	Books:	NO	Service Books:	NO

#### **Features**

AIR CON, CD PLAYER, CENTRAL LOCKING, POWER STEERING, POWER WINDOWS, SPARE WHEEL, BARN

DOORS, SLIDE DOOR

INSULATED VAN FITTED WITH 04/2003 EEZ-FREEZ REFRIGERATION UNIT

MOD: 2SN25 S/NO: A2819

IN CAB DIGITAL CONTROL

**ENGINE POWERED COMPRESSOR** 

(NO PLUG IN FACILITY) APPEARS OPERATIONAL

**KEY #27** 

#### **Tyres**





# 2003 MERCEDES SPRINTER 313 CDI HIGH ROOF FRIDGE VAN

### **Condition**

Location	Damage
REAR DOOR RIGHT	PANEL DAMAGE, HINGE STAYS BROKEN
REAR LEFT	HINGES BROKEN, PANEL DAMAGE, BENT
REAR DOOR RIGHT & REAR LEFT	NO INSULATION
REAR NUMBER PLATE	INCORRECT POSITION, ILLEGAL
INTERIOR LIGHT BODY	FAULTY
BATTERY	SOLD WITHOUT BATTERY
BATTERY STAYS	FASTENING BAR MISSING
ENGINE	OIL LEAKS
ENGINE	EXHAUST MANIFOLD GASKET REQUIRES REPLACEMENT
BRAKES	ALL PADS WORN TO METAL, DISCS DAMAGED
DISCS	REQUIRE REPLACEMENT/ MACHINING
RADIO	CODE LOCKED (NO BOOKS)
TRANSMISSION	SLOPPY - KNOCKS WHEN CLUTCH ENGAGES
CABIN A/C	FAN NOT WORKING - NO HEAT OR AIR CONDITIONING
SERVICE	OVERDUE BY 13,000kms (ACCORDING TO STICKER)
INTERIOR	MISSING DASH PARTS & PANELS. FUSES EXPOSED
TYRE - FRONT RIGHT	POOR, ON WEAR BARS REQUIRES REPLACING
TYRE - FRONT LEFT	BALD, ILLEGAL
TYRE - REAR LEFT	BALD, ILLEGAL
TYRE - REAR RIGHT	BALD, ILLEGAL
SPARE TYRE	EXCELLENT
SLIDING DOOR	LOCK BROKEN, ONLY OPENS FROM INSIDE
SLIDING DOOR	TRACK RUNNER BROKEN