

## 2001 HONDA CIVIC GLi SEDAN

### Asset Details

<b>Build Date:</b>	12/2001
<b>Compliance:</b>	
<b>Make:</b>	HONDA
<b>Model:</b>	CIVIC
<b>Variant:</b>	GLi
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	4 SPEED AUTOMATIC
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	SILVER
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	128,632	<b>Rego:</b>	WRT929	<b>State:</b>	SA	<b>Expiry:</b>	05/02/2020
<b>VIN:</b>	MRHES16502P040363	<b>PIN:</b>					
<b>Engine No:</b>	D17Z12910569	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	2	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, POWER STEERING, POWER WINDOWS, SPARE WHEEL

### Tyres

<b>Front LHS:</b>	Good	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	Good
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------

### Condition

Location	Damage
REAR DRIVERS SIDE LIGHT COVERS	CRACKED
FRONT LEFT BUMPER	SCRAPE
PASSENGER SIDE	REAR BUMPER AND QUARTER PANEL DO NOT LINE UP