

**ULTRA TUNE UNLEY**

ABN 76 1138 47653

PITSTOP ENTERPRISES PTY LTD

110 Unley Road

Unley SA 5061

PH 08 8271 5476

Welcome to Ultra Tune

Name:

IRIS (SA) PTY LTD

Company:

Address:

----- CHRIS WIGNALL---

471 PULTNEY ST

ADELAIDE SA 5000

Telephone: 1.

0427270253

2.

0427220854JO

A BREATH OF FRESH AIR

A litre of petrol causes 2.5 kilograms of carbon dioxide emissions which means 6 tonnes of CO² into our air every year. We will plant a tree through "Trees for Life" every time you have your car tuned and serviced at Ultra Tune.

Why?

A growing native tree absorbs 250 kilograms of CO² each year for 30 years, so you're helping the environment every time you have a tune. That's why at Ultra Tune we are in tune with you, your car and the environment.

Total Warranty on this vehicle cannot be honoured due to mechanical conditions noted in Technician Comments on Vehicle Service Report.

Manager's

Signature _____

Customer's

Signature _____

DATE	VEHICLE	REG'N No.	SPEEDO READ	CUST. REF.	JOB No. / INVOICE No.	FORM NUMBER
20/08/2018	MERCEDES GL320 C	S245BNN	215995	64414	64414/48189	

TAX INVOICE**VALUE**

VEHICLE TOWED IN WITH NO START, FOUND NO FUEL GETTING TO HIGH PRESSURE FUEL PUMP. CHECKED POWER SUPPLY TO LIFT PUMP - OKAY. LIFT PUMP WAS WORKING. REMOVED LIFT PUMP AND FOUND PUMP TO BE NOT SITTING SQUARE AND NOT SUBMERGED IN DIESEL. DIESEL FUEL LEVEL LOOKED LOW - READING BETWEEN 1/4 AND 1/2 ON DASH. CHECKED CALIBRATION OF FUEL GAUGE AND FOUND GAUGE TO BE READING 1/4 MORE THAN ACTUAL FUEL LEVEL. POSSIBLE FLOAT FAULT ON EITHER ONE OF THE FLOAT MODULES OR REAR SIGNAL ACQUISITION MODULE FAULT. FURTHER INVESTIGATION REQUIRED. RECOMMEND KEEPING FUEL LEVEL ABOVE 1/4 AT ALL TIMES UNTIL FAULT IS FIXED.

\$562.50

RE-ASSEMBLED FUEL PUMP MODULE AND REPLACED DIESEL FILTER. VEHICLE STARTED OKAY BUT DOES CRANK LONGER THAN USUAL BEFORE FIRING. (CONTACTED CUSTOMER WHO STATED THIS IS A PRIOR ISSUE/FAULT AND DOES NOT WANT IT INVESTIGATED OR LOOKED INTO.)

DIESEL FUEL FILTER

\$89.95

DIESEL FUEL

\$30.00

We would like to thank you for choosing ULTRA TUNE UNLEY for your servicing requirements
EFT BANK DETAILS - ACCOUNT NAME: PITSTOP ENTERPRISES PTY LTD BSB:085-005 ACCOUNT NUMBER:
584-111-686

TOTAL INCLUDING GST**\$682.45****Total Includes GST of \$ 62.04****Total Excluding GST \$ 620.41**