



VOLVO A25C ARTIC ARTICULATED 6x6 WATER CART

| Asset Details | S | | | | | | | |
|------------------------|------------|---------|---|-----------------------|-----------------------|----------|----|-----------------------|
| Build Date: | | | | | | | | |
| Make: | VOLVO | | | | | | | |
| Model: | A25C ARTIC | 0 | | | | | | |
| Series: | | | | | | | | |
| Drive Type: | ARTICULAT | ED | | | | | | |
| Axle Config: | 6x6 | | | | NO IN AVAIL | ABLE | | |
| Body Type: | WATER CA | RT | | | | | | |
| Gearbox: | | | | | | | | |
| Transmission: | AUTO | | | | | | | |
| Engine Make: | | | | | | | | |
| Engine Size: | | | | | | | | |
| Fuel Type: | DIESEL | | | | | | | |
| Diff Make / Size: | | | | | | | | |
| Suspension: | | | | | | | | |
| Ext Colour: | YELLOW | | | NO IMAGE AVAILABLE | NO IMAGE AVAILABLE | | | NO IMAGE AVAILABLE |
| Tyre Size: | 23.5 R25 | | | | | | | |
| Tyre Condition: | Poor | | | | | | | |
| Doors: | | Seats: | 1 | Length: | | Capacity | y: | |
| Volume: | | Height: | | Width: | | GVM: | | 40,270 |
| GCM: | | SWL: | | HP: | | Tare: | | |

Asset Identification PE 3172

| Odometer: | 98,281 | Rego: | LVP 021 | State: | SA | Expiry: | 17/12/2013 | |
|-------------------|------------------|-------|---------|--------|-------|----------------|------------|--|
| VIN: | 8090 | | | PIN: | | | | |
| Engine No: | TD73KCE997617410 | | | Hours: | 19457 | | | |
| Papers: | YES | Keys: | | Books: | YES | Service Books: | YES | |

Features

AC CABIN EX DUMP TRUCK FITTED WITH MILD STEEL TANK ESTIMATED 13,00 LITRE 3" PUMP, HONDA GX390 ELECTRIC START REAR SPRAYS & DRIBBLE BAR

Condition

| Location | Damage |
|------------|--------|
| PARK BRAKE | A/F |