



SERVICE TRAILER

Asset Details

| | |
|--------------|-----------------|
| Build Date: | |
| Make: | |
| Length: | |
| Sub Cat: | |
| Axle Config: | |
| Body Type: | SERVICE TRAILER |
| Model: | |
| ATM: | |
| Volume: | |
| Rating: | |
| Suspension: | |
| Axle Type: | |
| Rim Type: | |
| Tyre Size: | |
| Brakes: | |
| Coupling: | |



Asset Identification

| | | | | | | | |
|-----------|---------|----------------|-----|---------|--|---------|----|
| Rego: | TDG 633 | State: | | Expiry: | | Papers: | NO |
| Plant No: | | VIN / Chassis: | N/A | | | | |
| S/N: | | Hubometer: | | | | | |

Features

FITTED WITH LUBE SYSTEM, PETROL COMPRESSOR

Condition

| Location | Damage |
|----------|----------------|
| OVERALL | POOR CONDITION |
| TYRES | FLAT |