



## 2005 SUBARU LEGACY B-4 BL5BKCD STI SEDAN 2x4

Asset Details						
<b>Build Date:</b>	5/2005					
Compliance:	6/2005					
Make:	SUBARU					
Model:	LEGACY B-4					
Variant:	BL5BKCD	NO IMAGE AVAILABLE				
Series:	STI					
<b>Body Type:</b>	SEDAN					
Engine Size:	EJ20Y 2.5 LITRE					
Transmission:	5 SPEED MANUAL					
Fuel Type:	EFI PETROL					
Ext. Colour:	BLACK					
Int. Colour:	BLACK					
Doors:	4					
Seats:	5					
<b>Drive Type:</b>	2x4	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE		

#### **Asset Identification**

Odometer:	121334	Rego:	S197 AWH	State:		Expiry:	
VIN:	1F1BL5KD35G015209		PIN:				
Engine No:	<b>o</b> :		Hours:	0			
Papers:	NO	Keys:	1	Books:	NO	Service Books:	NO

#### **Features**

ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, IMMOBILISER, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF, ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, IMMOBILISER, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF, ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, IMMOBILISER, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF, ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, IMMOBILISER, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF

#### **Tyres**

Front LHS: Good Front RHS: Good Rear LHS: Good Rear RHS: Good Spa	: Good
---	--------





# 2005 SUBARU LEGACY B-4 BL5BKCD STI SEDAN 2x4

### **Condition**

Location	Damage
ENGINE	ENGINE COVER MISSING
BASH PLATE	MISSING
GEAR SHIFT KNOB	MISSING
ENGINE	WARNING LIGHT ILLUMINATED
RIGHT HAND SIDE WING MIRROR	DAMAGED
ENGINE	ENGINE COVER MISSING
BASH PLATE	MISSING
GEAR SHIFT KNOB	MISSING
ENGINE	WARNING LIGHT ILLUMINATED
RIGHT HAND SIDE WING MIRROR	DAMAGED
ENGINE	ENGINE COVER MISSING
BASH PLATE	MISSING
GEAR SHIFT KNOB	MISSING
ENGINE	WARNING LIGHT ILLUMINATED
RIGHT HAND SIDE WING MIRROR	DAMAGED
ENGINE	ENGINE COVER MISSING
BASH PLATE	MISSING
GEAR SHIFT KNOB	MISSING
ENGINE	WARNING LIGHT ILLUMINATED
RIGHT HAND SIDE WING MIRROR	DAMAGED