



# 2011 TOYOTA LANDCRUISER WORKMATE TRAY UTE 4x4

Asset Detail	s					
<b>Build Date:</b>	12/2011					
Compliance:						
Make:	TOYOTA					
Model:	LANDCRUISER					
Variant:	WORKMATE					
Series:			NO IMAGE AVAILABLI	E		
Body Type:	TRAY UTE					
Engine Size:	V8 TURBO					
Transmission:	5 SPEED MANUAL					
Fuel Type:	DIESEL					
Ext. Colour:	WHITE					
Int. Colour:						
Doors:	2					
Seats:	3					
<b>Drive Type:</b>	4x4	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE		

#### **Asset Identification BV156**

Odometer:	56000	Rego:	S456 APK	State:		Expiry:	07/03/2014
VIN:	JTELV71J400024439			PIN:			
Engine No:				Hours:	0		
Papers:	NO	Keys:	1	Books:	NO	Service Books:	NO

### **Features**

STEEL TRAY, TOW BAR, STEEL TRAY, TOW BAR, STEEL TRAY, TOW BAR, MINE SPEC FIRE SUPPRESSION, POLY BAR

#### **Tyres**

t LHS: Poor Front RHS: Poor Rear LHS: Poor Rear RHS: Poor Spare:
--





# **2011 TOYOTA LANDCRUISER WORKMATE TRAY UTE 4x4**

## **Condition**

Location	Damage
OVERALL	POOR CONDITION, CORROSION EVIDENT
BODY	DENTS & SCRATCHES THROUGHOUT
PASSENGER SEAT	NOT FITTED
ENGINE	WON'T TURN OVER
INTERIOR	POOR
OVERALL	POOR CONDITION, CORROSION EVIDENT
BODY	DENTS & SCRATCHES THROUGHOUT
PASSENGER SEAT	NOT FITTED
ENGINE	WON'T TURN OVER
INTERIOR	POOR
OVERALL	POOR CONDITION, CORROSION EVIDENT
BODY	DENTS & SCRATCHES THROUGHOUT
PASSENGER SEAT	NOT FITTED
ENGINE	WON'T TURN OVER
INTERIOR	POOR
OVERALL	POOR CONDITION, CORROSION EVIDENT
BODY	DENTS & SCRATCHES THROUGHOUT
PASSENGER SEAT	NOT FITTED
ENGINE	WON'T TURN OVER
INTERIOR	POOR