




## 2010 HYUNDAI I LOAD TQ V H-1 VAN 2x4

### Asset Details

<b>Build Date:</b>	6/2010
<b>Compliance:</b>	11/2010
<b>Make:</b>	HYUNDAI
<b>Model:</b>	I LOAD
<b>Variant:</b>	TQ V
<b>Series:</b>	H-1
<b>Body Type:</b>	VAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL
<b>Fuel Type:</b>	PETROL EFI
<b>Ext. Colour:</b>	WHITE
<b>Int. Colour:</b>	BLACK/GREY
<b>Doors:</b>	5
<b>Seats:</b>	3
<b>Drive Type:</b>	2x4



### Asset Identification

<b>Odometer:</b> 87,982	<b>Rego:</b> S595 AJN	<b>State:</b> SA	<b>Expiry:</b>
<b>VIN:</b> KMFWBX7RLAU265988	<b>PIN:</b>		
<b>Engine No:</b>	<b>Hours:</b> 0		
<b>Papers:</b> NO	<b>Keys:</b> 1	<b>Books:</b> NO	<b>Service Books:</b> NO

### Features

AIR BAG, AIR CON, CD PLAYER, POWER STEERING

### Condition

Location	Damage
EXTERIOR	R/H/S MINOR DENTS AND SCRATCHES
EXTERIOR	L/H/S MAJOR DENT IN DOOR AND SCRATCHES