



2006 DAEWOO/DOOSAN 140LCV SOLAR TRACKED EXCAVATOR

Asset Details

Tyre Condition: Doors:	Seats:	Length:	Mann Guy	Capacity:	
Tyre Size:		mgs			
Ext Colour:	ORANGE	NO IMAGE AVAILABLE	NO IMAGE	NO IMAGE	
Suspension:					
Diff Make / Size:					
Fuel Type:					
Engine Size:					
Engine Make:					
Transmission:					
Gearbox:					
Body Type:	EXCAVATOR	X			
Axle Config:					
Drive Type:	TRACKED	(
Series:	SOLAR				
Model:	140LCV				
Make:	DAEWOO/DOOSAN				
Build Date:	2006				

Asset Identification

Odometer:		Rego:	LVP 139	State:	SA	Expiry:
VIN:				PIN:	DHKHEBC0L600019	005
Engine No:				Hours:	7,273	
Papers:	NO	Keys:	1	Books:		Service Books:

Features

PLUMBED FOR HAMMER, 71kw, (PARTIAL BOOKS & SERVICE HISTORY)

Condition

Location	Damage
FRONT/BOTTOM SECTION CAB GLASS	DAMAGE MISSING

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1