

# 1990 MITSUBISHI PAJERO NG WAGON 4 X 4

## Asset Details

|                      |                 |
|----------------------|-----------------|
| <b>Build Date:</b>   | 4/1990          |
| <b>Compliance:</b>   | 4/1991          |
| <b>Make:</b>         | mitsubishi      |
| <b>Model:</b>        | PAJERO          |
| <b>Variant:</b>      | NG              |
| <b>Series:</b>       |                 |
| <b>Body Type:</b>    | WAGON           |
| <b>Engine Size:</b>  | 3 LTR V6        |
| <b>Transmission:</b> | 4 SPEED AUTO    |
| <b>Fuel Type:</b>    | PETROL          |
| <b>Ext. Colour:</b>  | BURGANDY        |
| <b>Int. Colour:</b>  | GREY CLOTH TRIM |
| <b>Doors:</b>        | 5               |
| <b>Seats:</b>        | 7               |
| <b>Drive Type:</b>   | 4 X 4           |



## Asset Identification

|                   |                   |               |         |               |     |                       |    |
|-------------------|-------------------|---------------|---------|---------------|-----|-----------------------|----|
| <b>Odometer:</b>  | 229,499           | <b>Rego:</b>  | VCZ 195 | <b>State:</b> | SA  | <b>Expiry:</b>        |    |
| <b>VIN:</b>       | JMFNG6Z45LJ004767 | <b>PIN:</b>   |         |               |     |                       |    |
| <b>Engine No:</b> | 6G72MM4861        | <b>Hours:</b> |         |               |     |                       |    |
| <b>Papers:</b>    | YES               | <b>Keys:</b>  | 2       | <b>Books:</b> | YES | <b>Service Books:</b> | NO |

## Features

AIR CON, ALLOY WHEELS, BULL BAR, ROOF RACKS, SIDE STEP, SPARE WHEEL, TOW BAR

## Tyres

|                   |         |                   |         |                  |         |                  |         |               |         |
|-------------------|---------|-------------------|---------|------------------|---------|------------------|---------|---------------|---------|
| <b>Front LHS:</b> | Average | <b>Front RHS:</b> | Average | <b>Rear LHS:</b> | Average | <b>Rear RHS:</b> | Average | <b>Spare:</b> | Average |
|-------------------|---------|-------------------|---------|------------------|---------|------------------|---------|---------------|---------|

## Condition

| Location                      | Damage                                     |
|-------------------------------|--|
| OVERALL CONDITION<br>EXTERIOR | PAINT DAMAGE, DENTS & SCRATCHES THROUGHOUT |