



# 2011 VOLVO A40F 6x6 ARTICULATED / WATER CART

## **Asset Details**

Build Date:	2011								
Make:	VOLVO								
Model:	A40F								
Series:									
Drive Type:	ive Type:								
Axle Config:	6x6								
Body Type:	ARTICULA CART	TED / WATER							
Gearbox:									
Transmission:									
Engine Make:	VOLVO D1	6H							
Engine Size:									
Fuel Type:									
Diff Make / Size:									
Suspension:			NO IMAGE						
Ext Colour:			AVAILABLE		AVAILABLE		AVAILABLE		
Tyre Size:									
Tyre Condition:									
Doors:	Seats:		Length:		Capacity:				
Volume:		Height:	Width:		GVM:				

### **Asset Identification WT4**

Odometer:	22,467kms	Rego:	S18SVS	State:	SA	Expiry:	22/03/2015
VIN:	VEC0A40FP0	0051511		PIN:			
Engine No:				Hours:	2,254		
Papers:	NO	Keys:	1	Books:		Service Books:	

HP:

Tare:

#### **Features**

GCM:

REAR SPRAYS, DRIBBLE BAR, HOSE REEL

SWL:

### Condition

Location	Damage	
NOTE	HYDRAULIC MOTOR TO PUMP DISCONNECTED	
MOTOR/PUMP	SUSPECT	

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1