



## 2000 (CP) MAZDA 121 121G P/CAR HATCH

### Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	2000
<b>Make:</b>	MAZDA
<b>Model:</b>	121
<b>Variant:</b>	121G P/CAR
<b>Series:</b>	
<b>Body Type:</b>	HATCH
<b>Engine Size:</b>	
<b>Transmission:</b>	3 SPEED AUTO
<b>Fuel Type:</b>	
<b>Ext. Colour:</b>	GREEN
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	311,926kms INDICATED	<b>Rego:</b>	NO PLATES	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JM0DW103200203524			<b>PIN:</b>			
<b>Engine No:</b>	B3313174		<b>Hours:</b>				
<b>Papers:</b>	YES	<b>Keys:</b>	2	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON

### Tyres

<b>Front LHS:</b>	Good	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	--

### Condition

Location	Damage
DUCO	PAINT CHIPS, SCRATCHES, DAMAGE
INTERIOR	STAINED
PILLAR	RUST