



1997 HYUNDAI COUPE

| Asset Details | | | | |
|--------------------|----------------|-----------------------|-----------------------|-----------------------|
| Build Date: | 8/1997 | | | |
| Compliance: | | | | |
| Make: | HYUNDAI | | | |
| Model: | COUPE | | | |
| Variant: | | NO IMAGE AVAILABLE | | |
| Series: | | | | |
| Body Type: | | | | |
| Engine Size: | 4 CYLINDER | | | |
| Transmission: | 5 SPEED MANUAL | | | |
| Fuel Type: | PETROL | | | |
| Ext. Colour: | RED | | | |
| Int. Colour: | GREY CLOTH | | | |
| Doors: | 2 | | | |
| Seats: | 5 | | | |
| Drive Type: | | NO IMAGE AVAILABLE | NO IMAGE AVAILABLE | NO IMAGE AVAILABLE |
| | | | | |

Asset Identification

| Odometer: | 204543 | Rego: | WPV 272 | State: | SA | Expiry: | |
|------------|-------------------|-------|---------|--------|-----|----------------|-----|
| VIN: | KMHKG21MPVU045674 | | | PIN: | | | |
| Engine No: | G4GMT236322 | | Hours: | | | | |
| Papers: | YES | Keys: | | Books: | YES | Service Books: | YES |

Tyres

Front LHS: Average Front RHS: Average Rear LHS: Average Rear RHS: Average Spare: Average

Condition

| Location | Damage |
|--------------------------------|--------|
| DRIVERS SIDE REAR QTR PANEL | DENTED |
| PAINTWORK | POOR |
| CLUTCH | NOISY |