

2006 VOLKSWAGEN PASSAT 3C SEDAN

Asset Details

| | |
|----------------------|-----------------|
| Build Date: | 1/2006 |
| Compliance: | 3/2006 |
| Make: | VOLKSWAGON |
| Model: | PASSAT |
| Variant: | |
| Series: | 3C |
| Body Type: | SEDAN |
| Engine Size: | FSI TURBO 147kw |
| Transmission: | AUTO |
| Fuel Type: | EFI |
| Ext. Colour: | GUN METAL GREY |
| Int. Colour: | BEIGE/BLACK |
| Doors: | 4 |
| Seats: | 5 |
| Drive Type: | FRONT |



Asset Identification

| | | | | | | | |
|-------------------|------------------------|--------------|---------|---------------|-----|-----------------------|-----|
| Odometer: | 95,605kms INDICATED | Rego: | XMZ 630 | State: | SA | Expiry: | |
| VIN: | WUWZZZ3CZ6P152602 | | | PIN: | | | |
| Engine No: | | | | Hours: | | | |
| Papers: | NO | Keys: | 0 | Books: | YES | Service Books: | YES |

Features

ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, **DEFECTED**

Tyres

| | | | | | | | | | |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|
| Front LHS: | Poor | Front RHS: | Poor | Rear LHS: | Good | Rear RHS: | Good | Spare: | Good |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|

Condition

| Location | Damage |
|----------------------------------|-------------------------------|
| FRONT END STEERING/SUSPENSION | DAMAGE |
| RHS WHEEL | BENT OUT & BRAKE DISC CRACKED |
| RHS FRONT GUARD | SLIGHT DAMAGE |
| RHS REAR WHEEL | BENT AT ODD ANGLE |