



# **1996 MITSUBISHI MAGNA EXECUTIVE SEDAN**

## **Asset Details**

| Build Date:   | 7/1996          |         |         |         |
|---------------|-----------------|---------|---------|---------|
| Compliance:   |                 |         |         |         |
| Make:         | MITSUBISHI      |         |         |         |
| Model:        | MAGNA           |         |         |         |
| Variant:      | EXECUTIVE       |         |         |         |
| Series:       |                 |         |         | E       |
| Body Type:    | SEDAN           |         |         |         |
| Engine Size:  | V6              |         |         |         |
| Transmission: | 4 SPEED AUTO    |         |         |         |
| Fuel Type:    | PETROL          |         |         |         |
| Ext. Colour:  | WHITE DUCO      |         |         |         |
| Int. Colour:  | GREY CLOTH TRIM |         |         |         |
| Doors:        | 4               |         |         |         |
| Seats:        | 5               |         |         |         |
| Drive Type:   |                 | NOIMAGE | NOIMAGE | NOIMAGE |
|               |                 |         |         |         |

## **Asset Identification**

| Odometer:  | 309,210            | Rego: | S172 BGO | State: | SA | Expiry:        | 22/04/2016 |
|------------|--------------------|-------|----------|--------|----|----------------|------------|
| VIN:       | 6MMTE6D42TT0114621 |       |          | PIN:   |    |                |            |
| Engine No: | 6G72M011310        |       |          | Hours: |    |                |            |
| Papers:    | YES                | Keys: | 1        | Books: | NO | Service Books: | NO         |

#### **Features**

AIR BAG, AIR CON, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, SPARE WHEEL, TOW BAR

## **Tyres**

| Front LHS: | Average | Front RHS: | Average | Rear LHS: | Average | Rear RHS: | Average | Spare: | Average |
|------------|---------|------------|---------|-----------|---------|-----------|---------|--------|---------|
| Condition  |         |            |         |           |         |           |         |        |         |

#### Condition

| Location            | Damage |
|---------------------|--------|
| BACK & FRONT BUMPER | DENTED |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1