

## VOLKSWAGEN BEETLE CARERA SEDAN

### Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	
<b>Make:</b>	VOLKSWAGEN
<b>Model:</b>	BEETLE
<b>Variant:</b>	CARERA
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	
<b>Transmission:</b>	4 SPEED MANUAL
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	BROWN
<b>Int. Colour:</b>	
<b>Doors:</b>	2
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>		<b>Rego:</b>	WZD 434	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>		<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>		<b>Books:</b>	NO	<b>Service Books:</b>	NO

### Features

NO COMPLIANCE PLATE SIGHTED, RESTORATION PROJECT OR SPARE PARTS, ENGINE INCOMPLETE, SPARE PARTS WITHIN, DOES NOT START OR RUN