



## 89 TOYOTA HILUX DUAL CAB UTE

## **Asset Details**

| Build Date:   | 89                |          |         |          |
|---------------|-------------------|----------|---------|----------|
| Compliance:   | 89                |          |         |          |
| Make:         | ΤΟΥΟΤΑ            |          |         |          |
| Model:        | HILUX             |          |         |          |
| Variant:      |                   |          |         |          |
| Series:       |                   |          |         | E        |
| Body Type:    | DUAL CAB UTE      |          |         |          |
| Engine Size:  | 4 CYLINDER PETROL |          |         |          |
| Transmission: | MANUAL 5 SPEED    |          |         |          |
| Fuel Type:    |                   |          |         |          |
| Ext. Colour:  | WHITE DUCO        |          |         |          |
| Int. Colour:  |                   |          |         |          |
| Doors:        |                   |          |         |          |
| Seats:        |                   |          |         |          |
| Drive Type:   |                   | NO IMAGE | NOIMAGE | NO IMAGE |
|               |                   |          |         |          |

## **Asset Identification**

| Odometer:  | 393,637 KMS       | Rego: | VMJ 590 | State: | SA | Expiry:        |    |
|------------|-------------------|-------|---------|--------|----|----------------|----|
| VIN:       | JT733RN8509002657 |       |         | PIN:   |    |                |    |
| Engine No: |                   |       | Hours:  |        |    |                |    |
| Papers:    | NO                | Keys: |         | Books: | NO | Service Books: | NO |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1