

## 1991 VOLVO 940 GL SEDAN

### Asset Details

<b>Build Date:</b>	1991
<b>Compliance:</b>	
<b>Make:</b>	VOLVO
<b>Model:</b>	940
<b>Variant:</b>	GL
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	3 SPEED AUTOMATIC TRANSMISSION
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	GOLD DUCO
<b>Int. Colour:</b>	BEIGE CLOTH
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	184,472kms SHOWING	<b>Rego:</b>	X0M 052	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	YV1944856N1055398	<b>PIN:</b>					
<b>Engine No:</b>	B230FB128956901034	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	3	<b>Books:</b>	NO	<b>Service Books:</b>	NO

### Features

AIR CON

### Tyres

<b>Front LHS:</b>	Poor	<b>Front RHS:</b>	Poor	<b>Rear LHS:</b>	Poor	<b>Rear RHS:</b>	Poor	<b>Spare:</b>	Poor
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------

### Condition

<b>Location</b>	<b>Damage</b>
PASSENGER DOORS	DENTED
OVERALL CONDITION	POOR