

## 2006 PEUGEOT 407 6D SALOON

### Asset Details

<b>Build Date:</b>	7/2006
<b>Compliance:</b>	10/2006
<b>Make:</b>	PEUGEOT
<b>Model:</b>	407
<b>Variant:</b>	6D
<b>Series:</b>	
<b>Body Type:</b>	SALOON
<b>Engine Size:</b>	2 LITRE V6 HDi TURBO
<b>Transmission:</b>	4 SPEED AUTO TRANSMISSION
<b>Fuel Type:</b>	DIESEL
<b>Ext. Colour:</b>	SILVER
<b>Int. Colour:</b>	BLACK
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	2x4



### Asset Identification

<b>Odometer:</b>	76,850kms SHOWING	<b>Rego:</b>	CC 684G	<b>State:</b>		<b>Expiry:</b>	31/10/2016
<b>VIN:</b>	VF36DUHJZJ21513835			<b>PIN:</b>			
<b>Engine No:</b>	10TRD10138729			<b>Hours:</b>			
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	NO

### Features

ABS, AIR BAG, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, FOG LAMPS, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TRACTION CONTROL, WARNING LIGHTS, HEATED SEATS & REAR PARKING SENSORS

### Tyres

<b>Front LHS:</b>	Poor	<b>Front RHS:</b>	Poor	<b>Rear LHS:</b>	Poor	<b>Rear RHS:</b>	Poor	<b>Spare:</b>	Good
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------

### Condition

Location	Damage
FRONT RHS WINDSCREEN	FITTING MISSING