


## 2011 HYUNDAI iLOAD H-1 VAN

### Asset Details

<b>Build Date:</b>	3/2011
<b>Compliance:</b>	
<b>Make:</b>	HYUNDAI
<b>Model:</b>	iLOAD
<b>Variant:</b>	H-1
<b>Series:</b>	
<b>Body Type:</b>	VAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	5
<b>Seats:</b>	3
<b>Drive Type:</b>	REAR WHEEL DRIVE



### Asset Identification

<b>Odometer:</b>	123,895kms SHOWING	<b>Rego:</b>	CB91RN	<b>State:</b>	NT	<b>Expiry:</b>	
<b>VIN:</b>	KMFWB7JLBU334870			<b>PIN:</b>			
<b>Engine No:</b>				<b>Hours:</b>			
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	

### Features

ABS, AIR BAG, AIR CON, CARGO BARRIER, CD PLAYER, CENTRAL LOCKING, DECALS, LADDER RACK, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TOW BAR, TRADEMANS FITOUT

### Condition

Location	Damage
REAR LH DOOR & RH DOOR	DENT
LH FRONT BUMPER	SCRATCHES
INTERIOR	SOILED