





# KOMATSU WA200-8 4x4 GALEO ARTICULATED WHEEL LOADER

## Asset Details

<b>Build Date:</b>	
<b>Make:</b>	KOMATSU
<b>Model:</b>	WA200-8
<b>Series:</b>	
<b>Drive Type:</b>	
<b>Axle Config:</b>	4x4
<b>Body Type:</b>	GALEO ARTICULATED WHEEL LOADER
<b>Gearbox:</b>	4 SPEED SELECTOR, VARIABLE SHIFT SPEED
<b>Transmission:</b>	AUTOMATIC TRANSMISSION
<b>Engine Make:</b>	KOMATSU
<b>Engine Size:</b>	6 CYLINDER TURBO
<b>Fuel Type:</b>	DIESEL
<b>Diff Make / Size:</b>	
<b>Suspension:</b>	
<b>Ext Colour:</b>	
<b>Tyre Size:</b>	
<b>Tyre Condition:</b>	



<b>Doors:</b>	<b>Seats:</b>	<b>Length:</b>	<b>Capacity:</b>
<b>Volume:</b>	<b>Height:</b>	<b>Width:</b>	<b>GVM:</b>
<b>GCM:</b>	<b>SWL:</b>	<b>HP:</b>	<b>Tare:</b>

## Asset Identification

<b>Odometer:</b>	<b>Rego:</b>	<b>State:</b>	<b>Expiry:</b>
<b>VIN:</b> KMNWA052V01067003	<b>PIN:</b>	<b>Hours:</b> 6,953hours INDICATED	
<b>Engine No:</b>	<b>Keys:</b>	<b>Books:</b> NO	<b>Service Books:</b> NO

## Features

TRACTION CONTROL  
8' GP BLADE BUCKET  
AUX HYDRAULICS  
BATTERY ISOLATOR  
A/C CAB



## KOMATSU WA200-8 4x4 GALEO ARTICULATED WHEEL LOADER

### Condition

Location	Damage
BODY	RUST EVIDENT, HEAVY IN CAB
LHR TYRE	SPLIT IN WALL, SLOW LEAK
OIL LEAKS	MINOR
BRAKE	PEDAL STICKY, OPERATIONAL, LIFT TO RELEASE