

## 2002 MITSUBISHI MAGNA ADVANCE V6 SEDAN

### Asset Details

|                      |            |
|----------------------|------------|
| <b>Build Date:</b>   | 11/2002    |
| <b>Compliance:</b>   |            |
| <b>Make:</b>         | MITSUBISHI |
| <b>Model:</b>        | MAGNA      |
| <b>Variant:</b>      | ADVANCE    |
| <b>Series:</b>       | V6         |
| <b>Body Type:</b>    | SEDAN      |
| <b>Engine Size:</b>  | V6 3.5L    |
| <b>Transmission:</b> | AUTO       |
| <b>Fuel Type:</b>    | UNLEADED   |
| <b>Ext. Colour:</b>  | DARK BLUE  |
| <b>Int. Colour:</b>  | GREY       |
| <b>Doors:</b>        | 4          |
| <b>Seats:</b>        | 5          |
| <b>Drive Type:</b>   |            |



### Asset Identification

|                   |                   |               |         |               |     |                       |            |
|-------------------|-------------------|---------------|---------|---------------|-----|-----------------------|------------|
| <b>Odometer:</b>  | 157759            | <b>Rego:</b>  | XAI 367 | <b>State:</b> | SA  | <b>Expiry:</b>        | 18/01/2017 |
| <b>VIN:</b>       | 6MMTJ8A422T054283 | <b>PIN:</b>   |         |               |     |                       |            |
| <b>Engine No:</b> | 6G74M293440       | <b>Hours:</b> |         |               |     |                       |            |
| <b>Papers:</b>    | YES               | <b>Keys:</b>  | 1       | <b>Books:</b> | YES | <b>Service Books:</b> | YES        |

### Features

AIR BAG, AIR CON, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, POWER WINDOWS, TOW BAR

### Tyres

|                   |      |                   |         |                  |         |                  |         |               |  |
|-------------------|------|-------------------|---------|------------------|---------|------------------|---------|---------------|--|
| <b>Front LHS:</b> | Good | <b>Front RHS:</b> | Average | <b>Rear LHS:</b> | Average | <b>Rear RHS:</b> | Average | <b>Spare:</b> |  |
|-------------------|------|-------------------|---------|------------------|---------|------------------|---------|---------------|--|

### Condition

| Location             | Damage                                    |
|----------------------|---|
| FRONT LEFT HAND SIDE | PAINT CRACKED/WORN AWAY FROM FRONT BUMPER |