

## 1997 LEXUS ES 300 SEDAN

### Asset Details

<b>Build Date:</b>	1/1997
<b>Compliance:</b>	
<b>Make:</b>	LEXUS
<b>Model:</b>	ES 300
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	V6 3000
<b>Transmission:</b>	3 SPEED AUTO
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	WHITE/METALLIC GREY
<b>Int. Colour:</b>	BEIGE LEATHER TRIM
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	376,218 KM	<b>Rego:</b>	AA-837Z	<b>State:</b>	SA	<b>Expiry:</b>	23/03/2017
<b>VIN:</b>	JT762XV2000043618	<b>PIN:</b>					
<b>Engine No:</b>	1MZ0397411	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	2	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CENTRAL LOCKING, CRUISE CONTROL, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF

### Condition

Location	Damage
PASSENGER SIDE REAR QUATER PANEL	DENT