



A Bank and a

VOLVO A35C ARTICULATED DUMP TRUCK

Ass	et	De	ta	ils

Asset Details	S			~	No.	and the second	
Build Date:			No.		APT	and the second	
Compliance:			-	-			Sec.
Make:	VOLVO					- 19 22 2	and the second second
Model:	A35C		THE REPORT				
Variant:					-		
Series:					E E	3	
Body Type:	ARTICULA TRUCK	TED DUMP					
Gearbox:			-			0 -	
Transmission:	AUTOMATI TRANSMIS					ME	
Engine Make:	VOLVO TD	122KME				Matson Gray Sti	range
Engine Size:					-	10	
Fuel Type:			The second second				
Diff Make / Size:							
Suspension:					A REPORT		
Ext Colour:							
Tyre Size:				Mason Gray Strange			Annon Cross Statters
Tyre Condition:			_				
Doors:		Seats:		Length:		Capacity:	
Volume:		Height:		Width:		GVM:	
GCM:		SWL:		HP:	360HP	Tare:	

Asset Identification

Odometer:	129,620kms INDICATED	Rego:		State:		Expiry:	
VIN:				PIN:	A35CV60381		
Engine No:	WVCXL12.0CE1		Hours:	19,156indicated			
Papers:		Keys:		Books:	NO	Service Books:	NO

Features

AIR CON, ROPS, FOPS

KEY #15

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 2





VOLVO A35C ARTICULATED DUMP TRUCK

Condition

Location	Damage
SERVICE STICKER	INDICATES PERFORMED @ 19,066H, DUE 19,500H
TAIL GATE	NONE, REMOVED
TRANSMISSION	DIPSTICK BROKEN, READING NOT AVAILABLE
STEER HUB RHS	WEEPING OIL
ENGINE BAY	VARIOUS OIL LEAKS