



# 2016 FORD TRANSIT HIGH ROOF 350L VO VAN

## Asset Details

| Asset Details |                                |                    |
|---------------|--------------------------------|--------------------|
| Build Date:   | 2/2016                         |                    |
| Compliance:   |                                |                    |
| Make:         | FORD                           |                    |
| Model:        | TRANSIT                        |                    |
| Variant:      | HIGH ROOF                      |                    |
| Series:       | 350L VO                        |                    |
| Body Type:    | VAN                            |                    |
| Engine Size:  | 4 CYLINDER 2.2 LITRE           |                    |
| Transmission: | 6 SPEED MANUAL<br>TRANSMISSION |                    |
| Fuel Type:    | TURBO DIESEL                   |                    |
| Ext. Colour:  | WHITE                          | Mason Gray Strange |
| Int. Colour:  | GREY                           |                    |
| Doors:        | 4                              |                    |
| Seats:        | 3                              |                    |
| Drive Type:   | REAR WHEEL DRIVE               |                    |

## Asset Identification

| Odometer:  | 57,515 kms<br>INDICATED | Rego: | S672 BJV | State: | SA | Expiry:        | 02/06/2017 |
|------------|-------------------------|-------|----------|--------|----|----------------|------------|
| VIN:       | WF0XXXTTGXFP43967       |       |          | PIN:   |    |                |            |
| Engine No: | FP43967                 |       | Hours:   |        |    |                |            |
| Papers:    | YES                     | Keys: | 1        | Books: | NO | Service Books: | NO         |

### **Features**

ABS, AIR BAG, AIR CON, BLUETOOTH, CARGO BARRIER, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, REVERSING CAMERA, GVM: 3,550kg, PVC FLOOR TUB

KEY # 26

### Condition

| Location | Damage                                |  |
|----------|---------------------------------------|--|
|          | REAR TAILGATE DAMAGE                  |  |
|          | DRIVERS & PASSENGER SIDE PANEL DAMAGE |  |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1