

## 2006 HYUNDAI ELANTRA SEDAN

### Asset Details

<b>Build Date:</b>	8/2006
<b>Compliance:</b>	
<b>Make:</b>	HYUNDAI
<b>Model:</b>	ELANTRA
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	AUTOMATIC TRANSMISSION
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	RED DUCO
<b>Int. Colour:</b>	BLACK
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	FWD



### Asset Identification

<b>Odometer:</b>	264,471kms SHOWING	<b>Rego:</b>	XLO 962	<b>State:</b>	SA	<b>Expiry:</b>	31/05/2017
<b>VIN:</b>	KMHDT41DR7U019779	<b>PIN:</b>					
<b>Engine No:</b>	G4GC6699833	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON, CD PLAYER, CENTRAL LOCKING, POWER STEERING, POWER WINDOWS, SPARE WHEEL, WARNING LIGHTS, KEY #61

### Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Average
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	---------

### Condition

Location	Damage
BODY	LARGE AMOUNT OF PAINT DAMAGE