

# 1997 MAZDA 121 HATCHBACK

## Asset Details

<b>Build Date:</b>	2/1997
<b>Compliance:</b>	
<b>Make:</b>	MAZDA
<b>Model:</b>	121
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	HATCHBACK
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	6 SPEED MANUAL
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	NOBLE GREEN
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



## Asset Identification

<b>Odometer:</b>	202026	<b>Rego:</b>	WJZ503	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JM0DV103300107141	<b>PIN:</b>					
<b>Engine No:</b>	33169480	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

## Features

AIR CON, CD PLAYER, CENTRAL LOCKING

## Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	--

## Condition

Location	Damage
FRONT PASSENGER SEAT	SEAT TORN
ROOF	PAINT FADED