

Location:



# 1993 MITSUBISHI MAGNA SEDAN

Asset Details					
<b>Build Date:</b>	5/1993				
Compliance:					
Make:	MITSUBISHI				
Model:	MAGNA				
Variant:					
Series:			NO IMAGE AVAILABLI	≡	
Body Type:	SEDAN				
Engine Size:	6 CYLINDER 3.5 LITRE				
Transmission:					
Fuel Type:	UNLEADED				
Ext. Colour:	DARK BLUE				
Int. Colour:	BLUE				
Doors:	4				
Seats:	5				
Drive Type:		NO IMAGE AVAILABLE	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE	

## **Asset Identification**

Odometer:	239012	Rego:	WPH566	State:	SA	Expiry:	
VIN:	6KMTR4D41P	T060006		PIN:			
<b>Engine No:</b>				Hours:			
Papers:	NO	Keys:	0	Books:	NO	Service Books:	NO

#### **Features**

AIR CON, POWER STEERING

#### **Tyres**

S: Average Rear LHS: Average Rear RHS: Average Spare:	Front RHS: Average Rear LHS: Average Rear RHS: Average Spare:	nt LHS: Average Front RHS: Average
-------------------------------------------------------	---------------------------------------------------------------	------------------------------------

### Condition

Location	Damage
INTERIOR	VERY DIRTY
FRONT RIGHT HAND SIDE	CASING OFF REAR VIEW MIRROR MISSING
ROOF	PAINT FADED, ANTENNA BROKEN
WINDSCREEN	CRACKED ON TOP RIGHT HAND SIDE