



# 6 x 4 TRAILER

Asset Details		
Build Date:		
Compliance:		
Make:		
Model:		
Variant:	6 x 4	
Series:		
Body Type:	TRAILER	
Engine Size:		
Transmission:		
Fuel Type:		
Ext. Colour:		
Int. Colour:		
Doors:		
Seats:		
Drive Type:		









# **Asset Identification**

Odometer:		Rego:	TBR273	State:	SA	Expiry:	
VIN:				PIN:			
<b>Engine No:</b>				Hours:			
Papers:	NO	Keys:		Books:	NO	Service Books:	NO

### **Features**

SPARE WHEEL, TIMBER TAILGATE, BALL HITCH

# **Tyres**

Front LHS:	Poor	Front RHS:	Poor	Rear LHS:	Rear RHS:	Spare:	Poor
------------	------	------------	------	-----------	-----------	--------	------

# Condition

Location	Damage
REAR RIGHT HAND SIDE	TAIL LIGHT BROKEN