



6 x 4 TRAILER

Asset Details	S			
Build Date:				
Compliance:				
Make:				
Model:				
Variant:	6 x 4			
Series:			NO IMAGE AVAILABL	E
Body Type:	TRAILER			
Engine Size:				
Transmission:				
Fuel Type:				
Ext. Colour:				
Int. Colour:				
Doors:				
Seats:				
Drive Type:		NO IMAGE AVAILABLE	NO IMAGE AVAILABLE	NO IMAGE AVAILABLE

Asset Identification

Odometer:		Rego:	TBR273	State:	SA	Expiry:	
VIN:				PIN:			
Engine No:				Hours:			
Papers:	NO	Keys:		Books:	NO	Service Books:	NO

Features

SPARE WHEEL, TIMBER TAILGATE, BALL HITCH

Tyres

Front LHS:	Poor	Front RHS:	Poor	Rear LHS:	Rear RHS:	Spare:	Poor

Condition

Location	Damage
REAR RIGHT HAND SIDE	TAIL LIGHT BROKEN