



## 1998 TOYOTA LANDCRUISER F2J75RP TRAYTOP 4x4

### Asset Details

|                      |                     |
|----------------------|---------------------|
| <b>Build Date:</b>   | 1998                |
| <b>Compliance:</b>   |                     |
| <b>Make:</b>         | TOYOTA              |
| <b>Model:</b>        | LANDCRUISER F2J75RP |
| <b>Variant:</b>      |                     |
| <b>Series:</b>       |                     |
| <b>Body Type:</b>    | TRAYTOP             |
| <b>Engine Size:</b>  | 4.5 LITRE           |
| <b>Transmission:</b> | MANUAL TRANSMISSION |
| <b>Fuel Type:</b>    | PETROL              |
| <b>Ext. Colour:</b>  | WHITE DUCO          |
| <b>Int. Colour:</b>  |                     |
| <b>Doors:</b>        |                     |
| <b>Seats:</b>        |                     |
| <b>Drive Type:</b>   | 4x4                 |



NO IMAGE  
AVAILABLE

**MGS**  
Mason Gray Strange



NO IMAGE  
AVAILABLE

**MGS**  
Mason Gray Strange



NO IMAGE  
AVAILABLE

**MGS**  
Mason Gray Strange



NO IMAGE  
AVAILABLE

**MGS**  
Mason Gray Strange

### Asset Identification

|                   |                         |               |         |               |    |                       |            |
|-------------------|-------------------------|---------------|---------|---------------|----|-----------------------|------------|
| <b>Odometer:</b>  | 300,000kms<br>INDICATED | <b>Rego:</b>  | WFD 427 | <b>State:</b> | SA | <b>Expiry:</b>        | 19/08/2017 |
| <b>VIN:</b>       | JT310UJ7508501111       | <b>PIN:</b>   |         |               |    |                       |            |
| <b>Engine No:</b> |                         | <b>Hours:</b> |         |               |    |                       |            |
| <b>Papers:</b>    | YES                     | <b>Keys:</b>  | 2       | <b>Books:</b> | NO | <b>Service Books:</b> | NO         |

### Features

AIR CON, BULL BAR, POWER STEERING, WINCH, ALLOY DROP SIDE TRAY

KEY #41

### Tyres

|                   |      |                   |      |                  |      |                  |      |               |  |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|--|
| <b>Front LHS:</b> | Poor | <b>Front RHS:</b> | Poor | <b>Rear LHS:</b> | Poor | <b>Rear RHS:</b> | Poor | <b>Spare:</b> |  |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|--|

### Condition

| Location            | Damage                          |
|---------------------|---------------------------------|
| BODY                | SCRATCHES, DENTS & RUST EVIDENT |
| CHASSIS             | CORROSION EVIDENT               |
| WINDSCREEN SURROUND | HEAVY RUST EVIDENT              |