



# 1993 MITSUBISHI MAGNA SEDAN

## Asset Details

<b>Build Date:</b>	5/1993
<b>Compliance:</b>	
<b>Make:</b>	MITSUBISHI
<b>Model:</b>	MAGNA
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	4 CYLINDER 2.6 LITRE
<b>Transmission:</b>	
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	DARK BLUE
<b>Int. Colour:</b>	BLUE
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



## Asset Identification

<b>Odometer:</b>	239012	<b>Rego:</b>	WPH566	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	6KMTR4D41PT060006			<b>PIN:</b>			
<b>Engine No:</b>				<b>Hours:</b>			
<b>Papers:</b>	NO	<b>Keys:</b>	0	<b>Books:</b>	NO	<b>Service Books:</b>	NO

## Features

AIR CON, POWER STEERING

## Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	--

## Condition

Location	Damage
INTERIOR	VERY DIRTY
FRONT RIGHT HAND SIDE	CASING OFF REAR VIEW MIRROR MISSING
ROOF	PAINT FADED, ANTENNA BROKEN
WINDSCREEN	CRACKED ON TOP RIGHT HAND SIDE