



# 1999 HOLDEN VT COMMODORE SEDAN

## Asset Details

|                      |              |
|----------------------|--------------|
| <b>Build Date:</b>   | 1999         |
| <b>Compliance:</b>   |              |
| <b>Make:</b>         | HOLDEN       |
| <b>Model:</b>        | VT COMMODORE |
| <b>Variant:</b>      |              |
| <b>Series:</b>       |              |
| <b>Body Type:</b>    | SEDAN        |
| <b>Engine Size:</b>  | 6 CYLINDER   |
| <b>Transmission:</b> |              |
| <b>Fuel Type:</b>    | PETROL       |
| <b>Ext. Colour:</b>  | SILVER       |
| <b>Int. Colour:</b>  | GREY CLOTH   |
| <b>Doors:</b>        | 4            |
| <b>Seats:</b>        | 5            |
| <b>Drive Type:</b>   |              |



## Asset Identification

|                   |                   |                     |                          |                |  |
|-------------------|-------------------|---------------------|--------------------------|----------------|--|
| <b>Odometer:</b>  |                   | <b>Rego:</b> WRZ592 | <b>State:</b> SA         | <b>Expiry:</b> |  |
| <b>VIN:</b>       | 6H8VTK69HXL432008 |                     | <b>PIN:</b>              |                |  |
| <b>Engine No:</b> |                   | <b>Hours:</b>       |                          |                |  |
| <b>Papers:</b> NO | <b>Keys:</b>      | <b>Books:</b> NO    | <b>Service Books:</b> NO |                |  |

## Features

POOR CONDITION, CAR HAS BEEN STRIPPED INSIDE & OUT, ENGINE COMPONENTS MISSING, SEATS, DASH & CENTRE CONSOLE MISSING, TO SUIT SPARE PARTS SALVAGE