

## 2012 ISUZU D-MAX LS DUAL CAB UTILITY 4x4

### Asset Details

<b>Build Date:</b>	2012
<b>Compliance:</b>	
<b>Make:</b>	ISUZU
<b>Model:</b>	D-MAX
<b>Variant:</b>	
<b>Series:</b>	LS
<b>Body Type:</b>	DUAL CAB UTILITY
<b>Engine Size:</b>	4 CYLINDER TURBO DIESEL INTERCOOLER
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	CHARCOAL
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	4x4



### Asset Identification

<b>Odometer:</b>	150,055kms SHOWING	<b>Rego:</b>	S204 ATK	<b>State:</b>		<b>Expiry:</b>	29/07/2017
<b>VIN:</b>	MPATFS85HCT104067	<b>PIN:</b>					
<b>Engine No:</b>	JS5403	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	2	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

KEY #20

### Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Average
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	---------

### Condition

Location	Damage
ENGINE	NOT RUNNING - ALL FAULTS
ENGINE	NO COMPRESSION - SUSPECTED BENT VALVES
TIMING CHAIN TENSIONER	SUSPECTED FAULTY / FAILED
EGR VALVE	ALL FAULTS