



ANTONIO CARRORO TGF9400 2x4 GLASSHOUSE TRACTOR

Asset Details

Build Date:		<div><div><div>NO IMAGE AVAILABLE</div></div><div></div></div>					
Make:	ANTONIO CARRORO						
Model:	TGF9400						
Series:							
Drive Type:	2x4						
Axle Config:							
Body Type:	GLASSHOUSE TRACTOR						
Gearbox:							
Transmission:							
Engine Make:							
Engine Size:							
Fuel Type:							
Diff Make / Size:							
Suspension:							
Ext Colour:							
Tyre Size:							
Tyre Condition:							
Doors:		Seats:		Length:		Capacity:	
Volume:		Height:		Width:		GVM:	
GCM:		SWL:		HP:		Tare:	

Asset Identification

Odometer:		Rego:	S92 SPM	State:		Expiry:	
VIN:		PIN:	NOT FOUND				
Engine No:	77B33286	Hours:	3,859hours INDICATED				
Papers:	NO	Keys:		Books:	NO	Service Books:	NO

Features

VM DIESEL, A/C CABIN, PTO, HYDRAULICS

Condition

Location	Damage
OVERALL	POOR STATE, NOT OPERATIONAL
TURBO CHARGER	REMOVED, DAMAGED
HOURLMETER	NOT ACCURATE 15%