



ANTONIO CARRORO TGF9400 2x4 GLASSHOUSE TRACTOR

Asset Details

Build Date:			
Make:	ANTONIO CARRORO		
Model:	TGF9400		
Series:			
Drive Type:	2x4		
Axle Config:			
Body Type:	GLASSHOUSE TRACTOR		
Gearbox:			
Transmission:			
Engine Make:			
Engine Size:			
Fuel Type:			
Diff Make / Size:			
Suspension:			
Ext Colour:			
Tyre Size:			
Tyre Condition:			
Doors:	Seats:	Length:	Capacity:
Volume:	Height:	Width:	GVM:
GCM:	SWL:	HP:	Tare:



Asset Identification

Odometer:	Rego:	S92 SPM	State:	Expiry:		
VIN:	PIN:		NOT FOUND			
Engine No:	77B33286	Hours:	3,859hours INDICATED			
Papers:	NO	Keys:	Books:	NO	Service Books:	NO

Features

VM DIESEL, A/C CABIN, PTO, HYDRAULICS

Condition

Location	Damage
OVERALL	POOR STATE, NOT OPERATIONAL
TURBO CHARGER	REMOVED, DAMAGED
HOURLMETER	NOT ACCURATE 15%