



## 2001 HONDA CR-V WAGON

### Asset Details

<b>Build Date:</b>	2001
<b>Compliance:</b>	
<b>Make:</b>	HONDA
<b>Model:</b>	CR-V
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	WAGON
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	NAPLES GOLD
<b>Int. Colour:</b>	GREY CLOTH INTERIOR
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	240,748	<b>Rego:</b>	WOE989	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JHLRD17401C203059	<b>PIN:</b>					
<b>Engine No:</b>	B20B8-3001898	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CARGO BARRIER, CD PLAYER, POWER STEERING, POWER WINDOWS, SPARE WHEEL

### Condition

Location	Damage
PAINTWORK	SCRATCHED & FADED IN PLACES
BODY	DENTS TO REAR QUARTER PANELS & BACK BUMPER