



## 2003 LINDE H35T-04 FORKLIFT

## **Asset Details**

| Build Date:       | 2003       |         |                    |  |  |
|-------------------|------------|---------|--------------------|--|--|
| Make:             | LINDE      |         |                    |  |  |
| Model:            | H35T-04    |         |                    |  |  |
| Series:           |            |         |                    |  |  |
| Drive Type:       |            |         |                    |  |  |
| Axle Config:      |            |         |                    |  |  |
| Body Type:        | FORKLIFT   |         | 7                  |  |  |
| Gearbox:          |            |         |                    |  |  |
| Transmission:     |            |         |                    |  |  |
| Engine Make:      |            |         |                    |  |  |
| Engine Size:      | 4 CYLINDER | - ma    |                    |  |  |
| Fuel Type:        | LPG        |         | Mason Gray Strange |  |  |
| Diff Make / Size: |            |         |                    |  |  |
| Suspension:       |            |         |                    |  |  |
| Ext Colour:       |            |         |                    |  |  |
| Tyre Size:        |            | 18 LOF  |                    |  |  |
| Tyre Condition:   |            |         |                    |  |  |
| Doors:            | Seats:     | Length: | Capacity:          |  |  |
| Volume:           | Height:    | Width:  | GVM:               |  |  |
| GCM:              | SWL:       | HP:     | Tare:              |  |  |

## **Asset Identification**

| Odometer:  |    | Rego: | State: |            | Expiry:        |    |
|------------|----|-------|--------|------------|----------------|----|
| VIN:       |    |       | PIN:   |            |                |    |
| Engine No: |    |       | Hours: | 3,898hours |                |    |
| Papers:    | NO | Keys: | Books: | NO         | Service Books: | NO |

## **Features**

3,500kG LIFT CAPACITY 4,323 mm LIFT HEIGHT **3 STAGE MAST, SIDE SHIFT** ENCLOSED CABIN PUNCTURE PROOF TYRES A/C,

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1