



# KOMATSU WA250-1 ARTICULATED LOADER

## Asset Details

<b>Build Date:</b>							
<b>Make:</b>	KOMATSU						
<b>Model:</b>	WA250-						
<b>Series:</b>							
<b>Drive Type:</b>							
<b>Axle Config:</b>							
<b>Body Type:</b>	ARTICULATED LOADER						
<b>Gearbox:</b>							
<b>Transmission:</b>							
<b>Engine Make:</b>							
<b>Engine Size:</b>	6 CYLINDER TURBO DIESEL						
<b>Fuel Type:</b>							
<b>Diff Make / Size:</b>							
<b>Suspension:</b>							
<b>Ext Colour:</b>							
<b>Tyre Size:</b>							
<b>Tyre Condition:</b>							
<b>Doors:</b>		<b>Seats:</b>		<b>Length:</b>		<b>Capacity:</b>	
<b>Volume:</b>		<b>Height:</b>		<b>Width:</b>		<b>GVM:</b>	
<b>GCM:</b>		<b>SWL:</b>		<b>HP:</b>		<b>Tare:</b>	



## Asset Identification

<b>Odometer:</b>		<b>Rego:</b>	WNM 861	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>		<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>	5,727hours				
<b>Papers:</b>	NO	<b>Keys:</b>		<b>Books:</b>	NO	<b>Service Books:</b>	NO

## Features

S/NO: 12478  
ISOLATOR, EXTINGUISHER, 2 WAY, 265cM GP BUCKET  
(LOCATED REGENCY ROAD, FERRYDEN PARK SA)

## Condition

Location	Damage
BROKEN WINDOW	
OVERALL	RUST EVIDENT