



# 1974 VOLVO 164 E SEDAN

## Asset Details

<b>Build Date:</b>	2/1974
<b>Compliance:</b>	
<b>Make:</b>	VOLVO
<b>Model:</b>	164
<b>Variant:</b>	E
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	6 CYLINDER
<b>Transmission:</b>	AUTOMATIC
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	WHITE
<b>Int. Colour:</b>	LIGHT BLUE
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



## Asset Identification

<b>Odometer:</b> 249774	<b>Rego:</b> WJE 641	<b>State:</b>	<b>Expiry:</b>
<b>VIN:</b> 1644369A104381	<b>PIN:</b>		
<b>Engine No:</b> 751	<b>Hours:</b>		
<b>Papers:</b> NO	<b>Keys:</b> 2	<b>Books:</b> NO	<b>Service Books:</b> NO

## Features

AIR CON, SPARE WHEEL, TOW BAR

## Tyres

<b>Front LHS:</b> Average	<b>Front RHS:</b> Poor	<b>Rear LHS:</b> Average	<b>Rear RHS:</b> Average	<b>Spare:</b> Average
---------------------------	------------------------	--------------------------	--------------------------	-----------------------

## Condition

Location	Damage
OVERALL	SURFACE RUST SPOTS
FRONT PASSENGER SIDE QUARTER	SLIGHT ACCIDENT DAMAGE AROUND HEADLIGHT TRIM