

# 1954 FORD CONSUL MK 1 SEDAN

## Asset Details

<b>Build Date:</b>	6/1954
<b>Compliance:</b>	
<b>Make:</b>	FORD
<b>Model:</b>	CONSUL
<b>Variant:</b>	
<b>Series:</b>	MK 1
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	3 SPEED MANUAL
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	CREAM
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



## Asset Identification

<b>Odometer:</b> 63278 MILES	<b>Rego:</b> RGD265	<b>State:</b>	<b>Expiry:</b>
<b>VIN:</b>		<b>PIN:</b>	
<b>Engine No:</b> EOTA42284		<b>Hours:</b>	
<b>Papers:</b> NO	<b>Keys:</b> 1	<b>Books:</b> NO	<b>Service Books:</b> NO

## Features

SPARE WHEEL

## Tyres

<b>Front LHS:</b> Poor	<b>Front RHS:</b> Poor	<b>Rear LHS:</b> Poor	<b>Rear RHS:</b> Poor	<b>Spare:</b> Poor
------------------------	------------------------	-----------------------	-----------------------	--------------------

## Condition

Location	Damage
OVERALL	RESTORATION PROJECT