



2017 NEW HOLLAND C227 SKID STEER LOADER

Asset Details

Assel Details		1		NAMES OF TAXABLE PARTY.	1	The second second	
Build Date:	2017		1.04		The second	THE REAL PROPERTY OF	Marca Radio
Make:	NEW HOLLAND						the i
Model:	C227						
Series:					ABY	NEW HOLLAND	1227
Drive Type:				1. 1. 1. 1. 1			ta management
Axle Config:					MEN HO	1	1 Anna
Body Type:	SKID STEE	SKID STEER LOADER					Carlor A
Gearbox:				Alex ~			2
Transmission:				NE X		2 Mine	and the second
Engine Make:			15459	S. S. Keine			
Engine Size:						and the second second	Anna anna anna anna anna anna anna anna
Fuel Type:			Contraction of the second		1 Sala	at the fact of the	
Diff Make / Size:							
Suspension:			A REAL AND				HEW HOLLOW
Ext Colour:			A		STRUE MET MOLLAND		
Tyre Size:							E Z
Tyre Condition:				Constant States		trin Only Sheetz	Mazan Gray Strange
Doors:		Seats:		Length:		Capacity:	
Volume:		Height:		Width:		GVM:	
GCM:		SWL:		HP:		Tare:	

Asset Identification

Odometer:		Rego:	S71 SDU	State:	Expiry:			
VIN:				PIN:	JAF0C227NGM4234	17		
Engine No:	000315070			Hours:	591 hours INDICATED			
Papers:	NO	Keys:	1	Books:	NO	Service Books:	NO	

Features

S/NO: NGM423417 **ON TRACKS** ATTACHMENTS TO INCLUDE 4 IN 1 BUCKET, WITH BOLT ON CUTTING EDGE, NORM ENGINEERING HIGH CAPACITY BUCKET, NORM ENGINEERING SET OF FORKS, HIMAC ENGINEERING.

KEY #39

(LOCATED AT PORT AUGUSTA)

Condition

Location	Damage
	DAMAGE TO FRONT DOOR FRAME & LIGHT COVER

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1