



## 2014 NISSAN PATHFINDER ST-L HYBRID SUV 4x4

### Asset Details

<b>Build Date:</b>	8/2014
<b>Compliance:</b>	
<b>Make:</b>	NISSAN
<b>Model:</b>	PATHFINDER
<b>Variant:</b>	ST-L HYBRID
<b>Series:</b>	
<b>Body Type:</b>	SUV
<b>Engine Size:</b>	
<b>Transmission:</b>	AUTOMATIC TRANSMISSION
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	SILVER DUCO
<b>Int. Colour:</b>	BLACK
<b>Doors:</b>	4
<b>Seats:</b>	
<b>Drive Type:</b>	4x4



### Asset Identification

<b>Odometer:</b>	60,226kms SHOWING	<b>Rego:</b>	XX 391X	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	5N1CR2MMXEC713579	<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>		<b>Books:</b>	YES	<b>Service Books:</b>	NO

### Features

AIR BAG, AIR CON, BLUETOOTH, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, FOG LAMPS, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF, TRACTION CONTROL, HEATED SEATS, REVERSE PARKING SENSORS  
BIRDS EYE VIEW REVERSE CAMERA

KEY #12

### Tyres

<b>Front LHS:</b>	Good	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	Good
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------

### Condition

Location	Damage
FRONT RIGHT BUMPER	SCRATCHED
BACK LEFT	SCRATCHED & DENTED DUCO