



# PEUGEOT 306 CABRIOLET

## Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	
<b>Make:</b>	PEUGEOT
<b>Model:</b>	306
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	CABRIOLET
<b>Engine Size:</b>	1.4 LITRE
<b>Transmission:</b>	AUTO
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	YELLOW DUCO
<b>Int. Colour:</b>	BLACK LEATHER INTERIOR
<b>Doors:</b>	2
<b>Seats:</b>	2
<b>Drive Type:</b>	



## Asset Identification

<b>Odometer:</b>	104617 INDICATED	<b>Rego:</b>	WSL 200	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	VF37DRFVP32444675	<b>PIN:</b>					
<b>Engine No:</b>	3000173	<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>	2	<b>Books:</b>	YES	<b>Service Books:</b>	YES

## Features

ABS, AIR BAG, AIR CON, CD PLAYER, SPARE WHEEL

## Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Average
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	---------

## Condition

Location	Damage
BONNET	SMALL DENTS TO FRONT EDGE